

序号	报告编号	发布日期	结论	影像资料
1	GX-B1495/20-2-24021~24033	2024. 2. 1	本次共检高压开关柜13台，13台所检项目合格。	
2	GX-B1495/20-2-24034~24042	2024. 2. 1	本次共检高压开关柜9台，9台所检项目合格。	

3	GX-B1495/20-2-24079~24080	2024. 2. 1	本次共检高压开关设备2台，2台所检项目合格。	
4	GX-B1495/20-2-24081	2024. 2. 1	所检项目合格。	

5	GX-B1495/20-2-24082	2024. 2. 1	所检项目合格。	
6	GX-B1495/20-2-24004	2024. 2. 1	所检项目合格。	

7	GX-B1495/20-2-24005	2024. 2. 1	所检项目合格。	 <p>2024/01/19</p>
8	GX-B1328/20-2-24005	2024. 2. 1	本次共检绝缘手套46只，46只所检项目合格。	 <p>2024/01/12</p>

9	GX-B1328/20-2-24006	2024. 2. 1	本次共检绝缘鞋42只，42只所检项目合格。	 A photograph showing two workers in a control room. One worker is kneeling on the floor, and the other is standing. They are surrounded by various safety equipment, including a red bucket, a yellow bucket, and several pairs of yellow and orange safety gloves. The date '2024/01/12' is visible in the bottom right corner of the photo.
10	GX-B1328/20-2-24007	2024. 2. 1	本次共检验电器2支，2支所检项目合格。	 A photograph showing a worker in a control room kneeling on the floor. The worker is wearing a red hard hat and a grey jacket. There is a blue stool and a red and yellow safety barrier in the foreground. The date '2024/01/12' is visible in the bottom right corner of the photo.

11	GX-B1328/20-2-24008	2024. 2. 1	本次共检绝缘杆5组，5组所检项目合格。	
12	GX-B1328/20-2-24009	2024. 2. 2	所检项目合格	

13	GX-B1328/20-2-24010	2024. 2. 2	所检项目合格	
14	GX-B1328/20-2-24011	2024. 2. 2	所检项目合格	

15	GX-B1321/20-2-24040~24043	2024. 2. 2	所检项目合格	 <p>2024/01/22</p>
16	GX-B1321/20-2-24030~24039	2024. 2. 2	所检项目合格	 <p>2024/01/19</p>

17	GX-B1321/20-2-24023~24029	2024. 2. 2	所检项目合格	
18	GX-B1321/20-2-24016~24022	2024. 2. 2	所检项目合格	

19	GX-B1321/20-2-24044	2024. 2. 2	所检项目合格	
20	GX-B1321/20-2-24045~24046	2024. 2. 2	所检项目合格	

21	GX-B1321/20-2-24047~24053	2024. 2. 2	所检项目合格	
22	GX-B1321/20-2-24010~24015	2024. 2. 2	所检项目合格	

23	GX-B1495/20-2-24006~24008	2024/2/1	本次共检高压防爆开关3台，3台所检项目合格。	
24	GX-B1495/20-2-24009~24012	2024/2/1	本次共检高压防爆开关4台，4台所检项目合格。	

25	GX-B1495/20-2-24013~24020	2024/2/1	本次共检高压防爆开关8台，8台所检项目合格。		
26	GX-B1495/20-2-24043~24050	2024/2/1	本次共检高压防爆开关8台，8台所检项目合格。		

27	GX-B1495/20-2-24051~24056	2024/2/1	本次共检高压防爆开关6台，6台所检项目合格。	
28	GX-B1495/20-2-24057~24060	2024/2/1	本次共检高压防爆开关4台，4台所检项目合格。	

29	GX-B1495/20-2-24061~24064	2024/2/1	本次共检高压防爆开关4台，4台所检项目合格。	 A photograph showing two workers in a tunnel environment. One worker in the foreground is wearing a blue jacket and a red hard hat, looking down at a device. Another worker is visible in the background, also wearing a red hard hat. The scene is dimly lit with a bright light source. A timestamp '2024/01/19' is visible in the bottom right corner of the image.
30	GX-B1495/20-2-24065~24078	2024/2/1	本次共检高压防爆开关14台，14台所检项目合格。	 A photograph showing a worker in a tunnel environment. The worker is wearing a dark jacket and a red hard hat, standing next to a large red piece of equipment. The tunnel is well-lit with overhead lights. A timestamp '2024/01/20' is visible in the bottom right corner of the image.

31	GX-B1310/21-2-24010	2024/2/2	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 <p>2024/01/20</p>
32	GX-B1310/21-2-24015	2024/2/2	符合标准要求	 <p>2024/01/22</p>

33	GX-B1310/21-2-24016	2024/2/2	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A worker in a blue uniform and red helmet is inspecting a large, dark-colored industrial component, possibly a turbine or engine part. The worker is standing in a narrow space between the component and another structure. A date stamp '2024.01.18' is visible in the bottom right corner of the image.
34	GX-B1310/21-2-24017	2024/2/2	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A worker in a blue uniform and red helmet is inspecting a large, blue industrial component, possibly a turbine or engine part. The worker is standing in a narrow space between the component and another structure. A date stamp '2024.01.19' is visible in the bottom right corner of the image.

35	GX-B1310/21-2-24018	2024/2/2	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
36	GX-B1427/21-2-24015	2024/2/2	符合标准要求	

37	GX-B1428/21-2-24016	2024/2/2	无缺陷迹痕显示	
38	GX-B1428/21-2-24017	2024/2/2	无缺陷迹痕显示	

39	GX-B1321/20-2-24065~24069	2024/2/4	所检项目合格	
40	GX-B1321/20-2-24070~24072	2024/2/4	所检项目合格	

41	GX-B1321/20-2-24054~24058	2024/2/4	所检项目合格	
42	GX-B1321/20-2-24059~24064	2024/2/4	所检项目合格	

43	GX-B1321/20-2-24073~24077	2024/2/4	所检项目合格	
44	GX-B1321/20-2-24078~24081	2024/2/4	所检项目合格	

45	GX-B1339/21-2-24001	2024/2/4	所检项目合格。		 A photograph showing two workers in blue uniforms and hard hats standing in a large industrial facility. They are positioned near a large piece of machinery with blue and red components. The floor is concrete and appears to have some oil stains. A date stamp '2024/01/06' is visible in the bottom right corner of the image.	
46	GX-B1339/21-2-24002	2024/2/4	所检项目合格。		 A photograph showing two workers in blue uniforms and hard hats standing in a large industrial facility. They are positioned near a large piece of machinery with blue and red components. The floor is concrete and appears to have some oil stains. A date stamp '2024/01/06' is visible in the bottom right corner of the image.	

47	GX-B1339/21-2-24003	2024/2/4	所检项目合格。		 A photograph showing industrial machinery in a factory setting. Two workers in blue uniforms and hard hats are visible. A date stamp '2024/01/08' is present in the bottom right corner.	
48	GX-B1339/21-2-24004	2024/2/4	所检项目合格。		 A photograph of a water treatment facility. A worker is visible on a platform overlooking a large tank of water. A date stamp '2024/01/06' is present in the bottom right corner.	

49	GX-B1339/21-2-24005	2024/2/4	所检项目合格。	
50	GX-B1339/21-2-24006	2024/2/4	所检项目合格。	

51	GX-B1339/21-2-24007	2024/2/4	所检项目合格。		 A photograph showing three workers in a dark tunnel. They are wearing hard hats and safety gear. One worker is kneeling on the ground, while two others stand nearby. Large pipes and machinery are visible in the background. A date stamp '2024/01/07' is visible in the bottom right corner of the image.	
52	GX-B1339/21-2-24008	2024/2/4	所检项目合格。		 A photograph showing workers in a tunnel. One worker is kneeling on the ground, and another is standing nearby. Large pipes and machinery are visible in the background. A date stamp '2024/01/07' is visible in the bottom right corner of the image.	

53	GX-B1339/21-2-24009	2024/2/4	所检项目合格。			
54	GX-B1339/21-2-24010	2024/2/4	所检项目合格。			

55	GX-B1416/22-2-24005	2024/2/4	综合判定：合格。	
56	GX-B1548/20-2-24001	2024. 2. 5	所检项目合格。	

57	GX-B1548/20-2-24002	2024. 2. 5	所检项目合格。	
58	GX-B1548/20-2-24006	2024. 2. 5	所检项目合格。	

59	GX-B1548/20-2-24003	2024. 2. 5	所检项目合格。	 A photograph showing two inspectors in red hard hats and winter jackets standing in front of a yellow truck. One inspector is holding a clipboard. A toolbox is open on the ground in front of them. The truck's license plate is visible and reads '桂B1548'. The background shows an outdoor industrial or construction site with a hillside. <p>2024/01/24</p>
60	GX-B1548/20-2-24004	2024. 2. 5	所检项目合格。	 A photograph showing two inspectors in red hard hats and winter jackets standing in front of a yellow truck. One inspector is holding a clipboard. A toolbox is open on the ground in front of them. The truck's license plate is visible and reads '桂B1548'. The background shows an outdoor industrial or construction site with a hillside. <p>2024/01/24</p>

61	GX-B1548/20-2-24005	2024. 2. 5	所检项目合格。		 <p>2024/01/24</p>	
62	GX-B1548/20-2-24007	2024. 2. 5	所检项目合格。		 <p>2024/01/25</p>	


63	GX-B1548/20-2-24008	2024. 2. 5	所检项目合格。	
64	GX-B1306/23-2-24004	2024. 2. 5	综合判定：合格。	

65	GX-B1306/23-2-24005	2024. 2. 5	综合判定：合格。	 <p>2024/01/20</p>
66	GX-B1306/23-2-24006	2024. 2. 5	综合判定：合格。	 <p>2024/01/20</p>

67	GX-B1534/20-2-24001	2024. 2. 5	所检项目合格。	
68	GX-B1534/20-2-24002	2024. 2. 5	所检项目合格。	

69	GX-B1534/20-2-24003	2024. 2. 5	所检项目合格。	 <p>2024/01/25</p>
70	GX-B1598/21-2-24001	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。	 <p>2024/01/24</p>

71	GX-B1598/21-2-24002	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。	 <p>A photograph showing a worker in a dark uniform with orange safety stripes and a harness, kneeling on a metal platform. The worker is focused on inspecting a steel cable. The background shows a complex metal structure, likely part of a crane or lifting equipment. A small date stamp '2024/01/24' is visible in the bottom right corner of the photo.</p>
72	GX-B1598/21-2-24003	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常。	 <p>A photograph showing a worker in a dark uniform with orange safety stripes, a red hard hat, and blue gloves, kneeling on a metal platform. The worker is inspecting a steel cable. The background shows a complex metal structure. A small date stamp '2024/01/24' is visible in the bottom right corner of the photo.</p>

73	GX-B1598/21-2-24004	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	
74	GX-B1598/21-2-24005	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	

75	GX-B1598/21-2-24006	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。	
76	GX-B1598/21-2-24007	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.17%，小于5%为正常。	

77	GX-B1598/21-2-24008	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.56%，小于5%为正常。	
78	GX-B1598/21-2-24009	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.13%，小于5%为正常。	

79	GX-B1598/21-2-24010	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.10%，小于5%为正常。	 <p>A close-up photograph of a steel wire rope being tested on a yellow machine. The rope is held in a metal fixture, and the machine's components are visible. A small date stamp '2024/01/25' is present in the bottom right corner of the image.</p>
80	GX-B1598/21-2-24011	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。	 <p>A photograph showing a worker in a white shirt and pink cap operating a yellow machine in a factory setting. The machine is part of a testing setup for steel wire ropes. A small date stamp '2024/01/26' is present in the bottom right corner of the image.</p>

81	GX-B1598/21-2-24012	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。	 A worker wearing a red hard hat and a grey jacket is working on a steel structure. The structure consists of vertical bars and horizontal beams. The worker is positioned in the center of the frame, looking down at something in their hands. The background shows a large industrial space with a blue railing and a yellow crane hook visible in the distance. A date stamp '2024/01/26' is visible in the bottom right corner of the image.
82	GX-B1598/21-2-24013	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.62%，小于5%为正常。	 Two workers in high-visibility yellow jackets and red hard hats are standing in an industrial setting. The worker in the foreground is holding a laptop computer. The worker in the background is looking at something. The setting appears to be a confined space or a narrow aisle with metal structures. A date stamp '2024/01/26' is visible in the bottom right corner of the image.

83	GX-B1598/21-2-24014	2024. 2. 6	实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常。	 <p>2024/01/26</p>
84	GX-B1422/21-2-24001	2024. 2. 6	所检项目合格。	 <p>2024/01/22</p>

85	GX-B1422/21-2-24002	2024. 2. 6	所检项目合格。	
86	GX-B1422/21-2-24003	2024. 2. 6	所检项目合格。	

87	GX-B1422/21-2-24004	2024. 2. 6	所检项目合格。	
88	GX-B1422/21-2-24005	2024. 2. 6	所检项目合格。	

89	GX-B1422/21-2-24006	2024. 2. 6	所检项目合格。	 <p>2024/01/23</p>
90	GX-B1422/21-2-24007	2024. 2. 6	所检项目合格。	 <p>2024/01/24</p>

91	GX-B1310/21-2-234011	2024/2/5	符合标准要求	
92	GX-B1310/21-2-234012	2024/2/5	符合标准要求	

93	GX-B1310/21-2-234013	2024/2/5	符合标准要求	
94	GX-B1310/21-2-234014	2024/2/5	符合标准要求	

95	GX-B1515/22-2-24001	2024. 2. 5	滚筒绳衬直径与钢丝绳直径之比小于50倍。除上述问题外，其余所检项目合格。			
96	GX-B1515/22-2-24002	2024. 2. 5	滚筒绳衬直径与钢丝绳直径之比小于50倍。除上述问题外，其余所检项目合格。			

97	GX-B1303/21-2-24001	2024. 2. 4	综合判定：合格。			
98	GX-B1303/21-2-24002	2024. 2. 4	综合判定：合格。			