


序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/21-9-22008	2022. 5. 7	所检项目合格。	 A photograph showing a red spherical float valve installed inside a metal cage. The cage is made of vertical bars and is mounted on a concrete wall. A timestamp '2022年3月25日' is visible in the bottom right corner of the image.
2	GX-B1341/21-9-22009	2022. 5. 7	所检项目合格。	 A close-up photograph of a large, black industrial fan or motor. The fan has several blades and is mounted on a metal frame. A timestamp '2022年3月23日' is visible in the bottom right corner of the image.
3	GX-B1342/21-9-22002	2022. 5. 7	所检项目合格。	 A photograph showing two workers in red uniforms and red hard hats standing in a tunnel. The tunnel walls are yellow and have some text on them, including '以人为本' and '安全第一'. A timestamp '2022.04.19' is visible in the bottom right corner of the image.

4	GX-B1340/21-9-22019~22020	2022. 5. 7	所检项目合格。	
5	GX-B1340/21-9-22021~22022	2022. 5. 6	所检项目合格。	