






序号	报告编号	发布日期	结论	影像资料
69	GX-B1310/21-5-22193	2022/7/6	符合标准要求	 A photograph showing a worker in a blue uniform and red hard hat working on a large industrial machine. The machine has a prominent red component. The worker is leaning over the machine, possibly inspecting or adjusting it. The date '2022/6/30' is visible in the bottom right corner of the image.
70	GX-B1310/21-5-22194	2022/7/6	符合标准要求	 A photograph showing a worker in a dark uniform and red hard hat working in a dark environment, possibly a tunnel or underground facility. The worker is holding a device, possibly a tablet or a specialized tool. The date '2022/06/30' is visible in the bottom left corner of the image.

71	GX-B1328/20-5-22099	2022.7.6	合格	 A document titled "说明" (Statement) with a red circular seal. The text on the document reads: "由于煤矿监控系统在监控范围内, 根据法律法规规定, 不得随意删除数据记录, 特此说明!" (Due to the coal mine monitoring system being within the monitoring range, according to laws and regulations, data records shall not be deleted at will. This is for information.) The seal is from "贵州煤矿安全监察局" (Guizhou Coal Mine Safety Supervision Bureau).
72	GX-B1328/20-5-22100	2022.7.6	合格	 A document titled "说明" (Statement) with a red circular seal. The text on the document reads: "由于煤矿监控系统在监控范围内, 根据法律法规规定, 不得随意删除数据记录, 特此说明!" (Due to the coal mine monitoring system being within the monitoring range, according to laws and regulations, data records shall not be deleted at will. This is for information.) The seal is from "贵州煤矿安全监察局" (Guizhou Coal Mine Safety Supervision Bureau).

73	GX-B1328/20-5-22094~22096	2022.7.8	所检项目合格	
74	GX-B1328/20-5-22101~22102	2022.7.8	所检项目合格	
75	GX-B1495/20-5-22063~22064	2022.7.8	所检项目合格	

76	GX-B1495/20-5-22084~22086	2022. 7. 8	所检项目合格	
77	GX-B1310/21-5-22184	2022/7/8	符合标椎要求	



78	GX-B1310/21-5-22183	2022/7/8	符合标准要求	
79	GX-B1310/21-5-22181	2022/7/8	符合标准要求	

80	GX-B1310/21-5-22180	2022/7/8	符合标准要求	
81	GX-B1310/21-5-22179	2022/7/8	符合标准要求	

82	GX-B1310/21-5-22177	2022/7/8	符合标准要求	
83	GX-B1310/21-5-22176	2022/7/8	符合标准要求	

84	GX-B1312/20-5-22518~22519	2022年7月8日	合格	
85	GX-B1323/21-5-22140~22141	2022年7月8日	合格	
86	GX-B1495/20-5-221518~221519	2022年7月8日	合格	

87	GX-B1303/21-5-22010	2022/7/8	合格	 <p>2022年6月13日</p>
88	GX-B1303/21-5-22011	2022/7/8	合格	 <p>2022年6月15日</p>

89	GX-B1303/21-5-22012	2022/7/8	合格	
90	GX-B1304/21-5-22006	2022/7/8	合格	

91	GX-B1304/21-5-22007	2022/7/8	合格	 <p>2022年6月18日</p>
92	GX-B1305/21-5-22005	2022/7/8	合格	 <p>2022年6月19日</p>

93	GX-B1305/21-5-22010	2022/7/8	合格	 <p>2022年6月16日</p>
94	GX-B1305/21-5-22004	2022/7/11	合格	 <p>2022年6月13日</p>

95	GX-B1305/21-5-22006	2022/7/11	合格	 <p>2022年6月14日</p>
96	GX-B1305/21-5-22007	2022/7/11	合格	 <p>2022年6月16日</p>

97	GX-B1305/21-5-22008	2022/7/11	合格	
98	GX-B1305/21-5-22009	2022/7/11	合格	

99	GX-B1305/21-5-22011	2022/7/11	合格	
100	GX-B1305/21-5-22012	2022/7/11	合格	

101	GX-B1307/21-5-22013	2021/7/12	综合判定：合格。	
102	GX-B1307/21-5-22014	2021/7/12	综合判定：合格。	
103	GX-B1307/21-5-22015	2021/7/12	综合判定：合格。	



104	GX-B1307/21-5-22016	2021/7/12	综合判定：合格。	
105	GX-B1307/21-5-22017	2021/7/12	综合判定：合格。	
106	GX-B1307/21-5-22018	2021/7/12	综合判定：合格。	

107	GX-B1307/21-5-22019	2021/7/12	综合判定：合格。	
108	GX-B1307/21-5-22020	2021/7/12	综合判定：合格。	
109	GX-B1307/21-5-22021	2021/7/12	综合判定：合格。	

110	GX-B1307/21-5-22022	2021/7/12	综合判定：合格。	 <p>A worker wearing a red hard hat and a blue t-shirt is inspecting a control panel. The panel has a red number '2' on it. A date stamp '2022/6/16' is visible in the bottom right corner of the photo.</p>
111	GX-B1307/21-5-22023	2021/7/12	综合判定：合格。	 <p>A worker wearing a red hard hat and a blue t-shirt is inspecting a control panel. The panel has a red number '1' on it. A date stamp '2022/6/16' is visible in the bottom right corner of the photo.</p>
112	GX-B1307/21-5-22024	2021/7/12	综合判定：合格。	 <p>A worker wearing a red hard hat and a blue t-shirt is inspecting a control panel. The panel has a red number '3' on it. A date stamp '2022/6/16' is visible in the bottom right corner of the photo.</p>

113	GX-B1307/21-5-22025	2021/7/12	综合判定：合格。	 A worker wearing a red hard hat and a blue t-shirt is standing in front of a green electrical cabinet. He is holding a handheld device, possibly a scanner or a data logger, and appears to be recording information. A QR code is visible on the cabinet door. The date stamp in the bottom right corner of the photo is 2022/6/16.
114	GX-B1307/21-5-22026	2021/7/12	综合判定：合格。	 A worker wearing a red hard hat and a blue t-shirt is working on a yellow electrical cabinet. He is holding a tool, possibly a screwdriver, and is focused on the task. The date stamp in the bottom right corner of the photo is 2022/6/17.
115	GX-B1307/21-5-22027	2021/7/12	综合判定：合格。	 A worker wearing a red hard hat and a blue t-shirt is standing in front of a white electrical cabinet. He is holding a document or a checklist and appears to be reviewing it. A red number '1' is visible on the cabinet door. The date stamp in the bottom right corner of the photo is 2022/6/17.

116	GX-B1307/21-5-22028	2021/7/12	综合判定：合格。	 A worker wearing a red hard hat and a blue long-sleeved shirt is standing in front of a control panel. He is looking at a screen or control knob on the panel. A date stamp '2022/6/17' is visible in the bottom right corner of the photo.
117	GX-B1307/21-5-22029	2021/7/12	综合判定：合格。	 A worker wearing a red hard hat and a blue long-sleeved shirt is standing in front of a control panel. He is looking at a screen or control knob on the panel. A date stamp '2022/6/17' is visible in the bottom right corner of the photo.
118	GX-B1307/21-5-22030	2021/7/12	综合判定：合格。	 A worker wearing a white protective suit, a red hard hat, and a yellow safety harness is standing in a control room. He is facing a control panel. A date stamp '2022/6/18' is visible in the bottom right corner of the photo.

119	GX-B1307/21-5-22031	2021/7/12	综合判定：合格。	
120	GX-B1307/21-5-22032	2021/7/12	综合判定：合格。	
121	GX-B1307/21-5-22033	2021/7/12	综合判定：合格。	