




序号	报告编号	发布日期	结论	影像资料
1	GX-B1340/21-8-22057	2022.08.11	所检项目合格	 <p>A photograph showing several workers in red hard hats and safety gear inspecting a large, orange industrial machine. The machine has a complex structure with pipes and a large cylindrical component. The workers are standing on a platform or scaffolding next to the machine. A timestamp '2022-07-21' is visible in the bottom right corner of the image.</p>
2	GX-B1340/21-8-22058	2022.08.11	所检项目合格	 <p>A photograph showing workers in red hard hats inspecting the same large orange industrial machine from a different perspective. The machine's complex piping and structure are clearly visible. A timestamp '2022-07-22' is visible in the bottom right corner of the image.</p>
3	GX-B1342/21-8-22017	2022.08.12	/	 <p>A photograph of a safety event. Several workers in orange safety suits and red hard hats are standing in front of a building entrance. A large red banner across the entrance reads '认真开展“安全生产月”和“安全生产万里行”活动' (Seriously carry out 'Safety Production Month' and 'Safety Production 10,000 Miles' activities). Other banners and posters are visible on the building walls, including one that says '安全是生命之本' (Safety is the foundation of life) and another that says '生产警钟长鸣' (Production bells ring constantly). A timestamp '2022-08-12' is visible in the bottom right corner of the image.</p>

4	GX-B1341-21/8-22081	2022年8月15日	综合判定：合格。	 
5	GX-B1341/21-8-22082	2022年8月15日	综合判定：合格。	
6	GX-B1341/21-8-22083	2022年8月15日	综合判定：合格。	