




序号	报告编号	发布日期	结论	影像资料
38	GX-B1310/21-Z-22059	2022/8/19	符合标准要求。	 A photograph showing an industrial interior, possibly a tunnel or underground facility. A worker wearing a blue uniform and a hard hat is visible in the center. The scene is dimly lit with some overhead lights. A date stamp '2022 07 21' is visible in the bottom right corner of the image.
39	GX-B1310/21-Z-22060	2022/8/19	符合标准要求。	 A photograph of a tunnel interior, likely a railway tunnel. The scene shows tracks running through the tunnel, with workers visible in the distance. The lighting is dark, with some bright spots from overhead lights. A date stamp '2022 07 21' is visible in the bottom right corner of the image.

40	GX-B1310/21-Z-22046	2022/8/19	符合标准要求。		 <p>2022 08 13</p>	
41	GX-B1310/21-Z-22047	2022/8/19	符合标准要求。		 <p>2022 08 14</p>	
42	GX-B1310/21-Z-22048	2022/8/19	符合标准要求。		 <p>2022 08 13</p>	

43	GX-B1310/21-Z-22049	2022/8/19	符合标准要求。		
44	GX-B1310/21-Z-22050	2022/8/19	符合标准要求。		
45	GX-B1310/21-Z-22051	2022/8/19	符合标准要求。		

46	GX-B1310/21-Z-22052	2022/8/19	符合标准要求。	 <p>2022 08 13</p>
47	GX-B1310/21-Z-22053	2022/8/19	符合标准要求。	 <p>2022 08 14</p>
48	GX-B1310/21-Z-22054	2022/8/19	符合标准要求。	 <p>2022 08 13</p>

49	GX-B1310/21-Z-22055	2022/8/19	符合标准要求。	 <p>2022 08 13</p>	
50	GX-B1310/21-Z-22056	2022/8/19	符合标准要求。	 <p>2022 08 13</p>	
51	GX-B1310/21-Z-22057	2022/8/19	符合标准要求。	 <p>2022 08 14</p>	

52	GX-B1310/21-Z-22058	2022/8/19	符合标准要求。		
53	GX-B1428/21-Z-22009	2022/8/19	符合标准要求。		
54	GX-B1428/21-Z-22010	2022/8/19	符合标准要求。		

55	GX-B1428/21-Z-22011	2022/8/19	符合标准要求。	
56	GX-B1428/21-Z-22012	2022/8/19	符合标准要求。	
57	GX-B1322/21-Z-22015~22020	2022/8/19	所检项目合格	

58	GX-B1381 / 20-Z-22015	2022/8/19	所检项目合格	 <p>2022 08 02</p>
59	GX-B1515 / 22-Z-22007	2022/8/19	所检项目合格	 <p>2022 07 20</p>