







序号	报告编号	发布日期	结论	影像资料（ JPG格式 ）
27	GX-B1312/20-3-22665	2022. 11. 10	所检项目合格	

28	GX-B1312/20-3-22666	2022. 11. 10	所检项目合格	 <p>2022年10月19日</p>
29	GX-B1321/20-3-221449~221450	2022. 11. 14	所检项目合格	 <p>2022.9.19</p>

30	GX-B1321/20-3-221451~221454	2022. 11. 14	所检项目合格	
31	GX-B1352/21-3-22283~22284	2022. 11. 11	所检项目合格	
32	GX-B1352/21-3-221070~221071	2022. 11. 11	所检项目合格	

33	GX-B1428/21-3-22036	2022年11月15日	所检项目合格	
34	GX-B1304/21-3-22003	2022. 11. 15	综合判定合格	
35	GX-B1310/21-3-22154	2022. 11. 16	所检项目合格	

36	GX-B1310/21-3-22155	2022. 11. 16	所检项目合格	
37	GX-B1427/21-3-22051	2022. 11. 16	所检项目合格	
38	GX-B1427/21-3-22052	2022. 11. 16	所检项目合格	

39	GX-B1312/20-3-22667~22682	2022. 11. 29	所检项目合格	
40	GX-B1312/20-3-22683~22697	2022. 11. 29	所检项目合格	

41	GX-B1312/20-3-22698~22709	2022. 11. 29	所检项目合格	
42	GX-B1312/20-3-22710~22712	2022. 11. 29	所检项目合格	

43	GX-B1312/20-3-22713~22724	2022. 11. 29	所检项目合格	
44	GX-B1312/20-3-22727~22733	2022. 11. 29	所检项目合格	

45	GX-B1312/20-3-22734~22738	2022. 11. 29	所检项目合格	
46	GX-B1323/21-3-22255~22269	2022. 11. 29	所检项目合格	

47	GX-B1323/21-3-22270~22284	2022. 11. 29	所检项目合格	
48	GX-B1416/22-3-22044	2022. 11. 29	综合判定：合格	

49	GX-B1416/22-3-22045	2022. 11. 29	综合判定：合格	
50	GX-B1416/22-3-22046	2022. 11. 29	综合判定：合格	




51	GX-B1416/22-3-22047	2022. 11. 29	综合判定：合格	
52	GX-B1416/22-3-22048	2022. 11. 29	综合判定：合格	

53	GX-B1416/22-3-22049	2022. 11. 29	综合判定：合格	
54	GX-B1416/22-3-22050	2022. 11. 29	综合判定：合格	

55	GX-B1416/22-3-22051	2022. 11. 29	综合判定：合格	
56	GX-B1416/22-3-22052	2022. 11. 29	综合判定：合格	

57	GX-B1416/22-3-22053	2022. 11. 29	综合判定：合格	
58	GX-B1416/22-3-22054	2022. 11. 29	综合判定：合格	

59	GX-B1561/20-3-22001	2022. 11. 29	所检项目合格	
60	GX-B1561/20-3-22002	2022. 11. 29	所检项目合格	

61	GX-B1561/20-3-22003	2022. 11. 29	所检项目合格	
62	GX-B1561/20-3-22004	2022. 11. 29	所检项目合格	
63	GX-B1499/21-3-22163	2022. 11. 29	所检项目合格	

64	GX-B1499/21-3-22164	2022. 11. 29	所检项目合格	
65	GX-B1499/21-3-22165	2022. 11. 29	所检项目合格	
66	GX-B1499/21-3-22166	2022. 11. 29	所检项目合格	

67	GX-B1499/21-3-22167	2022. 11. 29	所检项目合格	
68	GX-B1499/21-3-22168	2022. 11. 29	所检项目合格	
69	GX-B1499/21-3-22169	2022. 11. 29	所检项目合格	

70	GX-B1499/21-3-22170	2022. 11. 29	所检项目合格	
71	GX-B1499/21-3-22171	2022. 11. 29	所检项目合格	
72	GX-B1499/21-3-22172	2022. 11. 29	所检项目合格	

73	GX-B1499/21-3-22173	2022. 11. 29	所检项目合格	 <p>2022-11-29</p>
74	GX-B1499/21-3-22174	2022. 11. 29	所检项目合格	 <p>2022-11-29</p>
75	GX-B1499/21-3-22175	2022. 11. 29	所检项目合格	 <p>2022-11-29</p>

76	GX-B1499/21-3-22176	2022. 11. 29	所检项目合格	
77	GX-B1499/21-3-22177	2022. 11. 29	所检项目合格	
78	GX-B1499/21-3-22178	2022. 11. 29	所检项目合格	

79	GX-B1499/21-3-22179	2022. 11. 29	所检项目合格	
80	GX-B1499/21-3-22180	2022. 11. 29	所检项目合格	
81	GX-B1499/21-3-22181	2022. 11. 29	所检项目合格	

82	GX-B1499/21-3-22182	2022. 11. 29	所检项目合格	
83	GX-B1499/21-3-22183	2022. 11. 29	所检项目合格	
84	GX-B1499/21-3-22184	2022. 11. 29	所检项目合格	

85	GX-B1499/21-3-22185	2022. 11. 29	所检项目合格	
86	GX-B1499/21-3-22186	2022. 11. 29	所检项目合格	
87	GX-B1499/21-3-22187	2022. 11. 29	所检项目合格	

88	GX-B1499/21-3-22188	2022. 11. 29	所检项目合格	
89	GX-B1499/21-3-22189	2022. 11. 29	所检项目合格	
90	GX-B1499/21-3-22190	2022. 11. 29	所检项目合格	

91	GX-B1499/21-3-22191	2022. 11. 29	所检项目合格	
92	GX-B1499/21-3-22192	2022. 11. 29	所检项目合格	
93	GX-B1499/21-3-22193	2022. 11. 29	所检项目合格	

94	GX-B1499/21-3-22194	2022. 11. 29	所检项目合格	
95	GX-B1499/21-3-22195	2022. 11. 29	所检项目合格	
96	GX-B1499/21-3-22196	2022. 11. 29	所检项目合格	

97	GX-B1499/21-3-22197	2022. 11. 29	所检项目合格	 A worker wearing a grey jacket and a red hard hat is standing in a field with snow on the ground. They are holding a large, dark pipe. A yellow date stamp '2022-11-29' is visible in the bottom right corner of the photo.
98	GX-B1499/21-3-22198	2022. 11. 29	所检项目合格	 A worker wearing a grey jacket and a red hard hat is standing in a field with snow on the ground. A yellow date stamp '2022-11-29' is visible in the bottom right corner of the photo.
99	GX-B1499/21-3-22199	2022. 11. 29	所检项目合格	 A worker wearing a grey jacket and a red hard hat is operating a large pipe. To the left is a blue cylindrical tank, and to the right is a green metal frame. The ground is covered in snow. A yellow date stamp '2022-11-29' is visible in the bottom right corner of the photo.

100	GX-B1499/21-3-22200	2022. 11. 29	所检项目合格	
101	GX-B1499/21-3-22201	2022. 11. 29	所检项目合格	
102	GX-B1499/21-3-22202	2022. 11. 29	所检项目合格	

103	GX-B1539/20-3-22037	2022. 11. 29	所检项目合格	
104	GX-B1539/20-3-22038	2022. 11. 29	所检项目合格	

105	GX-B1423/20-3-22397	2022. 11. 29	综合判定：合格	
106	GX-B1423/20-3-22398	2022. 11. 29	综合判定：合格	
107	GX-B1423/20-3-22399	2022. 11. 29	综合判定：合格	

108	GX-B1423/20-3-22400	2022. 11. 29	综合判定：合格	 A person wearing a white protective suit and a white cap is seated in the driver's seat of a vehicle, operating the controls. The image is timestamped 2022.11.29.
109	GX-B1423/20-3-22401	2022. 11. 29	综合判定：合格	 A person wearing a white protective suit and a red cap is seated in the driver's seat of a blue vehicle, operating the controls. The image is timestamped 2022.11.27.
110	GX-B1423/20-3-22402	2022. 11. 29	综合判定：合格	 A person wearing a white protective suit and a white cap is seated in the driver's seat of a vehicle, operating the controls. The image is timestamped 2022.11.27.