

序号	报告编号	发布日期	结论	影像资料
40	GX-B1561/20-Y-22066	2023年2月2日	所检项目合格	 <p>A person wearing a white protective suit, a black helmet, and a red respirator mask is using a handheld device to inspect a metal cabinet. The person is standing in a room with a wooden door and a blue notice board in the background. A yellow timestamp '2022/12/18' is visible in the bottom right corner of the image.</p>
41	GX-B1539/22-Y-22225	2023年2月3日	所检项目合格	 <p>A yellow mining truck is parked in an outdoor area. Two workers wearing protective gear, including helmets and respirators, are standing in front of the truck. The background shows a large pile of material and a clear blue sky. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the image.</p>

42	GX-B1539/22-Y-22226	2023年2月3日	所检项目合格	 A yellow wheel loader is parked on a dirt surface. Two workers in safety gear are standing near the front of the machine. In the background, there is a large white building and a tall light pole. A yellow date stamp '2022/12/20' is visible in the bottom right corner of the photo.
43	GX-B1539/22-Y-22227	2023年2月3日	所检项目合格	 A yellow wheel loader is parked on a dirt surface. Two workers in safety gear are standing near the front of the machine. In the background, there is a large white building and a tall light pole. A yellow date stamp '2022/12/20' is visible in the bottom right corner of the photo.



44	GX-B1539/22-Y-22228	2023年2月3日	所检项目合格	 <p>2022/12/20</p>
45	GX-B1306/21-Y-22137	2023年2月3日	所检项目合格	 <p>2022/12/23</p>

46	GX-B1306/21-Y-22138	2023年2月3日	所检项目合格	
47	GX-B1306/21-Y-22139	2023年2月3日	所检项目合格	

48	GX-B1306/21-Y-22140	2023年2月3日	所检项目合格	 A photograph showing two workers in grey protective suits and black hoods inspecting a long, white cylindrical component. They are in an industrial environment with various pipes and machinery. A yellow timestamp '2022/12/23' is visible in the bottom right corner of the image.
49	GX-B1306/21-Y-22141	2023年2月3日	所检项目合格	 A photograph showing two workers in grey protective suits and black hoods inspecting a long, white cylindrical component. They are in an industrial environment with various pipes and machinery. A yellow timestamp '2022/12/23' is visible in the bottom right corner of the image.

50	GX-B1306/21-Y-22142	2023年2月3日	所检项目合格	 <p>2022/12/23</p>
51	GX-B1306/21-Y-22143	2023年2月3日	所检项目合格	 <p>2022/12/23</p>

52	GX-B1306/21-Y-22144	2023年2月3日	所检项目合格	 <p>2022/12/23</p>
53	GX-B1561/20-Y-22009	2023年2月2日	所检项目合格	 <p>2022/12/18</p>

54	GX-B1561/20-Y-22010	2023年2月2日	所检项目合格	 A photograph showing a worker in a white uniform and cap, holding a blue folder, standing in an industrial setting. The worker is positioned in front of a large piece of electrical equipment, possibly a control panel or a switchgear. The background shows a complex industrial environment with various pipes and structures. A yellow timestamp '2022/12/19' is visible in the bottom right corner of the image.
55	GX-B1561/20-Y-22011	2023年2月2日	所检项目合格	 A photograph showing a worker in a white uniform and cap, working on a piece of industrial equipment. The worker is positioned in front of a large piece of machinery, possibly a control panel or a switchgear. The background shows a complex industrial environment with various pipes and structures. A yellow timestamp '2022/12/19' is visible in the bottom right corner of the image.



56	GX-B1561/20-Y-22012	2023年2月2日	所检项目合格	
57	GX-B1515/20-Y-22007	2023年2月2日	除导向滚直径与钢丝绳直径之比超限外，其余所检项目合格。	

58	GX-B1385/21-Y-22047	2023年2月2日	所检项目合格	
59	GX-B1385/21-Y-22048	2023年2月2日	所检项目合格	

60	GX-B1385/21-Y-22049	2023年2月2日	所检项目合格	
61	GX-B1385/21-Y-22050	2023年2月2日	所检项目合格	

62	GX-B1385/21-Y-22051	2023年2月2日	所检项目合格	 <p>2022/12/19</p>
63	GX-B1385/21-Y-22052	2023年2月2日	所检项目合格	 <p>2022/12/19</p>

64	GX-B1385/21-Y-22053	2023年2月2日	所检项目合格	
65	GX-B1385/21-Y-22054	2023年2月2日	所检项目合格	

66	GX-B1423/20-Y-23401	2023年2月4日	综合判定：合格	
67	GX-B1423/20-Y-23402	2023年2月4日	综合判定：合格	

68	GX-B1423/20-Y-23403	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow and red X117 truck at a construction site. A person in a grey jacket is standing to the left of the truck, gesturing towards it. The truck has 'X117' and '117' visible on its front. A yellow timestamp '2023/1/16' is in the bottom right corner.</p>
69	GX-B1423/20-Y-23404	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow and red X113 truck at a construction site. Two people, one in a grey jacket and one in a camouflage jacket with a red helmet, are standing in front of the truck. The truck has 'X113' and '113' visible on its side. A yellow timestamp '2023/1/16' is in the bottom right corner.</p>

70	GX-B1423/20-Y-23405	2023年2月4日	综合判定：合格	
71	GX-B1423/20-Y-23406	2023年2月4日	综合判定：合格	




72	GX-B1423/20-Y-23407	2023年2月4日	综合判定：合格	 A yellow dump truck with a red stripe and the number 'X115' on the front. Two people are standing in front of the truck on a dirt surface. A date stamp '2023/1/16' is visible in the bottom right corner of the photo.
73	GX-B1423/20-Y-23408	2023年2月4日	综合判定：合格	 A yellow dump truck with a red stripe and a red flag on top. Two people are standing in front of the truck on a dirt surface. A date stamp '2023/1/16' is visible in the bottom right corner of the photo.



74	GX-B1423/20-Y-23409	2023年2月4日	综合判定：合格	
75	GX-B1423/20-Y-23410	2023年2月4日	综合判定：合格	

76	GX-B1423/20-Y-23411	2023年2月4日	综合判定：合格	
77	GX-B1423/20-Y-23412	2023年2月4日	综合判定：合格	

78	GX-B1423/20-Y-23413	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow and red truck, likely a construction vehicle, parked on a dirt surface. A person in a white uniform is standing next to the truck, possibly inspecting it. The date stamp '2023/1/16' is visible in the bottom right corner of the image.</p>
79	GX-B1423/20-Y-23414	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow and red truck, similar to the one in the first row, parked on a dirt surface. Two people, one in a red jacket and one in a grey jacket, are standing in front of the truck. The date stamp '2023/1/16' is visible in the bottom right corner of the image.</p>

80	GX-B1423/20-Y-23415	2023年2月4日	综合判定：合格	
81	GX-B1423/20-Y-23416	2023年2月4日	综合判定：合格	

82	GX-B1423/20-Y-23417	2023年2月4日	综合判定：合格	
83	GX-B1423/20-Y-23418	2023年2月4日	综合判定：合格	

84	GX-B1423/20-Y-23419	2023年2月4日	综合判定：合格	
85	GX-B1423/20-Y-23420	2023年2月4日	综合判定：合格	

86	GX-B1423/20-Y-23421	2023年2月4日	综合判定：合格	 A yellow X192 truck is shown in a desert environment. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/18' is visible in the bottom right corner of the image.
87	GX-B1423/20-Y-23422	2023年2月4日	综合判定：合格	 A yellow X1210 truck is shown in a desert environment. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/18' is visible in the bottom right corner of the image.



88	GX-B1423/20-Y-23423	2023年2月4日	综合判定：合格	
89	GX-B1423/20-Y-23424	2023年2月4日	综合判定：合格	

90	GX-B1423/20-Y-23425	2023年2月4日	综合判定：合格	 A photograph showing a person wearing a grey jacket and a dark cap sitting inside the cab of a yellow construction vehicle, possibly a loader or excavator. The person is looking towards the camera. The vehicle's door is open. A yellow timestamp '2023/1/18' is visible in the bottom right corner of the image.
91	GX-B1423/20-Y-23426	2023年2月4日	综合判定：合格	 A photograph of a yellow construction vehicle, likely a loader, parked on a dirt field. Several workers in red jackets and hard hats are standing around the vehicle. One worker in the foreground is wearing a high-visibility yellow vest over a red jacket. A yellow timestamp '2023/1/18' is visible in the bottom right corner of the image.

92	GX-B1423/20-Y-23427	2023年2月4日	综合判定：合格	 <p>A yellow XCMG off-road truck, model K1252, is shown from a side-rear perspective. A person in a grey jacket and dark pants is standing next to the truck, holding a clipboard and looking at the vehicle. The truck has the numbers '1 2 5' on its side. A yellow timestamp '2023/1/18' is visible in the bottom right corner of the photo.</p>
93	GX-B1423/20-Y-23428	2023年2月4日	综合判定：合格	 <p>A yellow XCMG off-road truck, model K1218, is shown from a front-three-quarter view. Two people are standing in front of the truck; one is wearing a red hard hat and a high-visibility vest, and the other is in a grey jacket. The truck has 'XCMG' and 'K1218' visible on its side. A yellow timestamp '2023/1/18' is visible in the bottom right corner of the photo.</p>

94	GX-B1423/20-Y-23429	2023年2月4日	综合判定：合格	
95	GX-B1423/20-Y-23430	2023年2月4日	综合判定：合格	

96	GX-B1423/20-Y-23431	2023年2月4日	综合判定：合格	
97	GX-B1423/20-Y-23432	2023年2月4日	综合判定：合格	

98	GX-B1423/20-Y-23433	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow truck, likely a dump truck, parked in a desert-like environment. A person in a grey uniform is standing next to the truck, holding a device. The date stamp in the bottom right corner of the photo is 2023/1/17.</p>
99	GX-B1423/20-Y-23434	2023年2月4日	综合判定：合格	 <p>A photograph of a yellow truck, likely a dump truck, with the license plate X1263. Two people are standing in front of the truck. The date stamp in the bottom right corner of the photo is 2023/1/17.</p>

100	GX-B1423/20-Y-23435	2023年2月4日	综合判定：合格	
-----	---------------------	-----------	---------	---