

序号	报告编号	发布日期	结论	影像资料
461	GX-B1428/21-Y-23043	2023年4月6日	无缺陷迹痕显示。	 A photograph showing two workers in blue work clothes and red hard hats. They are standing in front of a large, orange-painted industrial machine, possibly a boiler or pressure vessel. One worker is looking into an opening of the machine. A yellow timestamp '2023/3/6' is visible in the bottom right corner of the image.
462	GX-B1428/21-Y-23044	2023年4月6日	无缺陷迹痕显示。	 A photograph showing a worker in a grey jacket and red hard hat. The worker is inspecting a large, orange-painted industrial machine. A white label with the Chinese character '机' (machine) is visible on the machine's surface. A yellow timestamp '2023/3/27' is visible in the bottom right corner of the image.

463	GX-B1428/21-Y-23045	2023年4月6日	无缺陷迹痕显示。	 <p>A photograph showing a worker in a blue uniform with a yellow stripe and a red helmet. The worker is positioned in front of a large, orange, curved industrial structure, possibly a part of a turbine or engine. The worker appears to be performing maintenance or inspection. A date stamp '2023/3/29' is visible in the bottom right corner of the image.</p>
464	GX-B1428/21-Y-23046	2023年4月6日	无缺陷迹痕显示。	 <p>A close-up photograph of a large, curved, reddish-pink industrial component. The surface appears smooth and metallic. The lighting is somewhat dim, highlighting the texture and color of the material. A date stamp '2023/3/27' is visible in the bottom right corner of the image.</p>

465	GX-B1310/21-Y-23043	2023年4月6日	符合标准要求。	
466	GX-B1310/21-Y-23044	2023年4月6日	符合标准要求。	

467	GX-B1310/21-Y-23045	2023年4月6日	符合标准要求。	
468	GX-B1310/21-Y-23046	2023年4月6日	符合标准要求。	

469	GX-B1495/20-Y-23995~ 231008	2023年4月5日	本次共检高压防爆开关 14台，14台高压防爆开关所 检项目合格。	 A photograph showing several workers in blue uniforms and red hard hats working on high-voltage electrical equipment in a mine. The workers are focused on their tasks, and the equipment is complex with various cables and components. A date stamp '2023/3/9' is visible in the bottom right corner of the image.
470	GX-B1495/20-Y-231009~ 231017	2023年4月5日	本次共检高压防爆开关 9台，9台高压防爆开关所检 项目合格。	 A photograph showing workers in blue uniforms and red hard hats inspecting a large red high-voltage switch cabinet. The cabinet has a '10kV' label and a '停电' (Stop Power) sign. The workers are using tools and equipment to perform the inspection. A date stamp '2023/3/10' is visible in the bottom right corner of the image.

471	GX-B1495/20-Y-231018~ 231027	2023年4月5日	本次共检高压防爆开关 10台，10台高压防爆开关所 检项目合格。	
472	GX-B1423/20-Y-231854	2023年4月2日	综合判定：合格	

473	GX-B1329/21-Y-23013~23026	2023年4月5日	本次共检氧化锌避雷器 14组， 14组所检项目合格。	 A photograph showing two technicians in blue work clothes and red hard hats inspecting a piece of electrical equipment, likely a zinc oxide arrester, in a workshop setting. A date stamp '2023/3/9' is visible in the bottom right corner of the image.
474	GX-B1329/21-Y-23027~23035	2023年4月5日	本次共检氧化锌避雷器9组， 9组所检项目合格。	 A photograph showing three technicians in blue work clothes and red hard hats inspecting a piece of electrical equipment, likely a zinc oxide arrester, in a workshop setting. A date stamp '2023/3/10' is visible in the bottom right corner of the image.

475	GX-B1329/21-Y-23036~23045	2023年4月5日	本次共检氧化锌避雷器 10组， 10组所检项目合格。	 A photograph showing a worker in a blue uniform and red helmet working on a red electrical cabinet. The worker is using a tool, possibly a screwdriver, to work on the internal components of the cabinet. The date 2023/3/14 is visible in the bottom right corner of the image.
476	GX-B1404/20-Y—23003	2023年4月4日	所检电网谐波电压总 谐波畸变率、各次谐波电压 含有率、谐波电流符合GB/T 14549-1993 《电能质量 公 用电网谐波》要求。	 A photograph showing a worker in a white jacket and red helmet working on a white electrical cabinet. The worker is using a tool, possibly a screwdriver, to work on the internal components of the cabinet. The date 2023/3/12 is visible in the bottom right corner of the image.

477	GX-B1404/20-Y-23004	2023年4月4日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>A photograph showing a worker in a white jacket and red helmet working on electrical equipment in a control room. The worker is standing next to a yellow and red control panel. The date '2023-3-13' is visible in the bottom right corner of the image.</p>
478	GX-B1515/22-Y-23006	2023年4月4日	所检项目合格。	 <p>A photograph showing a worker in a white jacket working on a large industrial machine. The worker is standing next to a green and yellow machine. The date '2023-3-13' is visible in the bottom right corner of the image.</p>

479	GX-B1308/21-Y-23006	2023年4月5日	所检项目合格。	 <p>A photograph showing a worker in a full-body orange protective suit and a red helmet. The worker is standing in a dark, confined industrial space, possibly a tunnel or a large pipe, and appears to be inspecting or working on some equipment. A date stamp '2023/3/13' is visible in the bottom right corner of the image.</p>
480	GX-B1499/21-Y-23045	2023年4月5日	所检项目合格。	 <p>A photograph showing a worker in a full-body orange protective suit and a red helmet. The worker is standing on a green platform with yellow safety lines. To the right, there is a large piece of industrial machinery with green pipes and a blue door in the background. A date stamp '2023/3/13' is visible in the bottom right corner of the image.</p>


481	GX-B1499/21-Y-23046	2023年4月5日	所检项目合格。	 A photograph showing a worker in a full-body orange protective suit and a red helmet. The worker is standing on a yellow safety line on a green floor, looking down at a piece of equipment. The background shows a confined space with some blue panels. A yellow timestamp '2023/3/13' is visible in the bottom right corner of the photo.
482	GX-B1499/21-Y-23047	2023年4月5日	所检项目合格。	 A photograph showing a worker in a full-body orange protective suit and a red helmet. The worker is standing in a confined space, looking at a piece of equipment. The background shows some blue panels and a red and white striped pole. A yellow timestamp '2023/3/13' is visible in the bottom right corner of the photo.

483	GX-B1308/21-Y-23007	2023年4月5日	所检项目合格。	
484	GX-B1499/21-Y-23048	2023年4月5日	所检项目合格。	

485	GX-B1499/21-Y-23049	2023年4月5日	所检项目合格。	
486	GX-B1499/21-Y-23050	2023年4月5日	所检项目合格。	


487	GX-B1539/22-Y-23023	2023年3月31日	所检项目合格。	
488	GX-B1539/22-Y-23024	2023年3月31日	所检项目合格。	

489	GX-B1539/22-Y-23025	2023年3月31日	所检项目合格。	
490	GX-B1539/22-Y-23026	2023年3月31日	所检项目合格。	

491	GX-B1539/22-Y-23027	2023年3月31日	所检项目合格。	
492	GX-B1312/20-Y-23122	2023年4月4日	所检项目合格。	

493	GX-B1312/20-Y-23123	2023年4月4日	所检项目合格。	
494	GX-B1312/20-Y-23124~23125	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

495	GX-B1312/20-Y-23126	2023年4月4日	所检项目合格。	
496	GX-B1312/20-Y-23127	2023年4月4日	所检项目合格。	

497	GX-B1312/20-Y-23128~23129	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
498	GX-B1312/20-Y-23130	2023年4月4日	所检项目合格。	

499	GX-B1312/20-Y-23131	2023年4月4日	所检项目合格。	
500	GX-B1312/20-Y-23132	2023年4月4日	所检项目合格。	

501	GX-B1312/20-Y-23133	2023年4月4日	所检项目合格。	
502	GX-B1312/20-Y-23134	2023年4月4日	所检项目合格。	


503	GX-B1312/20-Y-23135	2023年4月4日	所检项目合格。	
504	GX-B1312/20-Y-23136~23137	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

505	GX-B1312/20-Y-23138	2023年4月4日	所检项目合格。	
506	GX-B1312/20-Y-23139	2023年4月4日	所检项目合格。	

507	GX-B1312/20-Y-23140	2023年4月4日	所检项目合格。	
508	GX-B1312/20-Y-23141	2023年4月4日	所检项目合格。	

509	GX-B1312/20-Y-23142~23143	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A photograph showing a worker in a red uniform and helmet working on a transformer at night. The worker is wearing a red helmet with a headlamp and a red uniform with reflective stripes. The background is dark, and the worker is illuminated by the headlamp. The date "2023/3/10" is visible in the bottom right corner of the image.
510	GX-B1312/20-Y-23144	2023年4月4日	所检项目合格。	 A photograph showing a worker in a red uniform and helmet working on a transformer at night. The worker is wearing a red helmet with a headlamp and a red uniform. The worker is kneeling on the ground, and there are some tools and equipment around. The background is dark, and the worker is illuminated by the headlamp. The date "2023/3/10" is visible in the bottom right corner of the image.

511	GX-B1312/20-Y-23145~23146	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
512	GX-B1312/20-Y-23147~23148	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

513	GX-B1312/20-Y-23149	2023年4月4日	所检项目合格。	
514	GX-B1312/20-Y-23150~23151	2023年4月4日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	


515	GX-B1321/20-Y-23131~23145	2023年4月5日	本次共检验电力电缆15条，15条电力电缆所检项目合格。	
516	GX-B1321/20-Y-23146~23150	2023年4月5日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	

517	GX-B1321/20-Y-23151~23160	2023年4月5日	本次共检验电力电缆10条，10条电力电缆所检项目合格。	
518	GX-B1321/20-Y-23161~23171	2023年4月5日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	

519	GX-B1321/20-Y-23172~23183	2023年4月5日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	
520	GX-B1321/20-Y-23184~23195	2023年4月5日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	

521	GX-B1321/20-Y-23196~23207	2023年4月5日	本次共检验电力电缆 12条，12条电力电缆所检项 目合格。	
522	GX-B1321/20-Y-23208~23219	2023年4月5日	本次共检验电力电缆 12条，12条电力电缆所检项 目合格。	

523	GX-B1321/20-Y-23220~23230	2023年4月5日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	
524	GX-B1321/20-Y-23231~23243	2023年4月5日	本次共检验电力电缆13条，13条电力电缆所检项目合格。	

525	GX-B1321/20-Y-23244~23245	2023年4月5日	本次共检验电力电缆6条， 6条电力电缆所检项目合格。	 <p>A photograph showing a worker in a red helmet and grey uniform working on a yellow electrical cabinet. The worker is standing on a platform and appears to be inspecting or working on the interior of the cabinet. The date '2023/3/4' is visible in the bottom right corner of the image.</p>
526	GX-B1321/20-Y-23246~23251	2023年4月5日	本次共检验电力电缆 10条，10条电力电缆所检项 目合格。	 <p>A photograph showing a worker in a red helmet working in a dark, confined space, possibly a tunnel or underground area. The worker is wearing a red helmet and a dark uniform. The date '2023/3/5' is visible in the bottom right corner of the image.</p>

527	GX-B1321/20-Y-23252~23253	2023年4月5日	本次共检验电力电缆6条， 6条电力电缆所检项目合格。	 A photograph showing a worker in a white protective suit and red helmet working inside an orange electrical cabinet. The worker is standing on a platform, and the cabinet is open, revealing internal components. A date stamp '2023/3/6' is visible in the bottom right corner of the image.
528	GX-B1321/20-Y-23254~23257	2023年4月5日	本次共检验电力电缆8条， 8条电力电缆所检项目合格。	 A photograph showing a worker in a white protective suit and red helmet working on a dark electrical cabinet. The worker is crouching and looking into the cabinet. A date stamp '2023/3/6' is visible in the bottom right corner of the image.

529	GX-B1321/20-Y-23258~23264	2023年4月5日	本次共检验电力电缆9条， 9条电力电缆所检项目合格。	
530	GX-B1321/20-Y-23265~23269	2023年4月5日	本次共检验电力电缆7条， 7条电力电缆所检项目合格。	