

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|----------|--------|---|
| 202 | GX-B1306/21-1-23001 | 2023/4/1 | 所检项目合格 |  A technician in a dark jacket is working on a laptop. Another person is partially visible in the background. A yellow date stamp '2023/01/04' is in the bottom left corner. |
| 203 | GX-B1306/21-1-23002 | 2023/4/1 | 所检项目合格 |  A technician is kneeling in a server room, working on equipment. A yellow date stamp '2023/01/04' is in the bottom left corner. |
| 204 | GX-B1306/21-1-23003 | 2023/4/1 | 所检项目合格 |  A technician is kneeling next to a large server cabinet, working on equipment. A yellow date stamp '2023/01/04' is in the bottom left corner. |
| 205 | GX-B1306/21-1-23004 | 2023/4/1 | 所检项目合格 |  A technician is kneeling next to a large server cabinet, working on equipment. A yellow date stamp '2023/01/04' is in the bottom left corner. |

| | | | | |
|-----|---------------------|-----------|----------|---|
| 206 | GX-B1306/21-1-23005 | 2023/4/1 | 所检项目合格 |  |
| 207 | GX-B1306/21-1-23006 | 2023/4/1 | 所检项目合格 |  |
| 208 | GX-B1305/21-1-23004 | 2023/4/11 | 综合判定：合格。 |  |
| 209 | GX-B1423/20-1-23156 | 2023/4/12 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 210 | GX-B1423/20-1-23157 | 2023/4/12 | 综合判定：合格 |  |
| 211 | GX-B1423/20-1-23158 | 2023/4/12 | 综合判定：合格 |  |
| 212 | GX-B1423/20-1-23159 | 2023/4/12 | 综合判定：合格 |  |
| 213 | GX-B1423/20-1-23160 | 2023/4/12 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 214 | GX-B1423/20-1-23161 | 2023/4/12 | 综合判定：合格 |  |
| 215 | GX-B1423/20-1-23162 | 2023/4/12 | 综合判定：合格 |  |
| 216 | GX-B1423/20-1-23163 | 2023/4/12 | 综合判定：合格 |  |
| 217 | GX-B1423/20-1-23164 | 2023/4/12 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-----------|---------|--|
| 218 | GX-B1423/20-1-23165 | 2023/4/12 | 综合判定：合格 |  A photograph of a red truck with two people standing in front of it. The date '2023.03.09' is visible in the bottom right corner of the photo. |
| 219 | GX-B1423/20-1-23166 | 2023/4/12 | 综合判定：合格 |  A photograph of a red truck with two people standing in front of it. The date '2023.03.09' is visible in the bottom right corner of the photo. |
| 220 | GX-B1423/20-1-23167 | 2023/4/12 | 综合判定：合格 |  A photograph of a red truck with two people standing in front of it. The date '2023.03.09' is visible in the bottom right corner of the photo. |
| 221 | GX-B1423/20-1-23168 | 2023/4/12 | 综合判定：合格 |  A photograph of a red truck with two people standing in front of it. The date '2023.03.09' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 222 | GX-B1500/21-1-23024 | 2023/4/12 | 综合判定：合格 |  |
| 223 | GX-B1500/21-1-23025 | 2023/4/12 | 综合判定：合格 |  |
| 224 | GX-B1500/21-1-23026 | 2023/4/12 | 综合判定：合格 |  |
| 225 | GX-B1520/20-1-23007 | 2023/4/13 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------------|-------------|---------|---|
| 226 | GX-B1520/20-1-23008 | 2023/4/13 | 综合判定：合格 |  |
| 227 | GX-B1350/21-1-23007 | 2023. 4. 11 | 所检项目合格 |  |
| 228 | GX-B1350/21-1-23008 | 2023. 4. 11 | 所检项目合格 |  |
| 229 | GX-B1351/21-1-23001-23002 | 2023. 4. 11 | 所检项目合格 |  |

| | | | | |
|-----|---------------------------|-------------|--------------|---|
| 230 | GX-B1352/21-1-23091-23104 | 2023. 4. 11 | 所检项目合格 |  |
| 231 | GX-B1352/21-1-23105-23120 | 2023. 4. 14 | 所检项目合格 |  |
| 232 | GX-B1354/20-1-23001 | 2023. 4. 11 | 电网接地电容电流符合规定 |  |
| 233 | GX-B1310/21-1-23023 | 2023/4/12 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 234 | GX-B1310/21-1-23024 | 2023/4/12 | 符合标准要求 |  |
| 235 | GX-B1427/21-1-23023 | 2023/4/12 | 符合标准要求 |  |
| 236 | GX-B1427/21-1-23024 | 2023/4/12 | 符合标准要求 |  |
| 237 | GX-B1428/21-1-23025 | 2023/4/12 | 无缺陷迹痕显示 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 238 | GX-B1428/21-1-23026 | 2023/4/12 | 无缺陷迹痕显示 |  |
| 239 | GX-B1423/20-1-23169 | 2023/4/13 | 综合判定：合格 |  |
| 240 | GX-B1423/20-1-23170 | 2023/4/13 | 综合判定：合格 |  |
| 241 | GX-B1423/20-1-23171 | 2023/4/13 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-----------|---------|--|
| 242 | GX-B1423/20-1-23172 | 2023/4/13 | 综合判定：合格 |  A yellow truck is parked on a dirt surface. Two people are standing near the front of the truck. A date stamp '2023.03.10' is visible in the bottom right corner of the photo. |
| 243 | GX-B1423/20-1-23173 | 2023/4/13 | 综合判定：合格 |  A yellow truck is parked on a dirt surface. Two people are standing near the front of the truck. A date stamp '2023.03.10' is visible in the bottom right corner of the photo. |
| 244 | GX-B1423/20-1-23174 | 2023/4/13 | 综合判定：合格 |  A yellow truck is parked on a dirt surface. Two people are standing near the front of the truck. A date stamp '2023.03.10' is visible in the bottom right corner of the photo. |
| 245 | GX-B1423/20-1-23175 | 2023/4/13 | 综合判定：合格 |  A yellow truck is parked on a dirt surface. Two people are standing near the front of the truck. A date stamp '2023.03.10' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 246 | GX-B1423/20-1-23176 | 2023/4/13 | 综合判定：合格 |  |
| 247 | GX-B1423/20-1-23177 | 2023/4/13 | 综合判定：合格 |  |
| 248 | GX-B1423/20-1-23178 | 2023/4/13 | 综合判定：合格 |  |
| 249 | GX-B1423/20-1-23179 | 2023/4/13 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 250 | GX-B1423/20-1-23180 | 2023/4/13 | 综合判定：合格 |  |
| 251 | GX-B1301/21-1-23002 | 2023/4/14 | 综合判定：合格 |  |
| 252 | GX-B1300/20-1-23003 | 2023/4/14 | 综合判定：合格 |  |
| 253 | GX-B1306/21-1-23016 | 2023/4/14 | 所检项目合格 |  |

| | | | | |
|-----|---------------------|-----------|--------|---|
| 254 | GX-B1306/21-1-23017 | 2023/4/14 | 所检项目合格 |  |
| 255 | GX-B1306/21-1-23018 | 2023/4/14 | 所检项目合格 |  |
| 256 | GX-B1306/21-1-23019 | 2023/4/14 | 所检项目合格 |  |