

序号	报告编号	发布日期	结论	影像资料
44	GX-B1312/20-2-22266~22267	2022/9/6	所检项目合格	
45	GX-B1312/20-2-22255~22265	2022/9/6	所检项目合格	
46	GX-B1360/21-2-22014~22018	2022. 9. 6	合格	

47	GX-B1495/20-2-222319~222333	2022/9/7	所检项目合格	 <p>A photograph showing a worker in a red hard hat and light-colored shirt standing next to a blue utility vehicle. The vehicle has yellow cables coiled on its bed. In the background, there is a green electrical cabinet with a warning sign. The date '2022/07/28' is visible in the bottom right corner of the photo.</p>
48	GX-B1495/20-2-222334~222345	2022/9/7	所检项目合格	 <p>A photograph showing a worker in a red hard hat and light-colored shirt kneeling on the floor, working on electrical equipment. The worker is wearing a red hard hat and a light-colored shirt. The equipment is a large, white, metal cabinet. The date '2022/07/28' is visible in the bottom right corner of the photo.</p>

49	GX-B1495/20-2-222399~222410	2022/9/7	所检项目合格	
50	GX-B1495/20-2-222411~222420	2022/9/7	所检项目合格	

51	GX-B1495/20-2-222346~222351	2022/9/7	所检项目合格	
52	GX-B1495/20-2-222352~222362	2022/9/7	所检项目合格	

53	GX-B1495/20-2-222363~222369	2022/9/7	所检项目合格	
54	GX-B1495/20-2-222370~222379	2022/9/7	所检项目合格	

55	GX-B1495/20-2-222380~222389	2022/9/7	所检项目合格	
56	GX-B1495/20-2-222390~222398	2022/9/7	所检项目合格	