

序号	报告编号	发布日期	结论	影像资料
1	GX-B1378/22-F-23067~F-23070	2023. 4. 6	所检项目合格	
2	GX-B1378/22-F-23071	2023. 4. 6	所检项目合格	


3	GX-B1378/22-F-23079~F-23083	2023. 4. 11	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. One person is standing and pointing towards a piece of equipment or a display on a desk. The other person is leaning over the desk, looking at the equipment. The date stamp in the bottom right corner of the image is 2023/3/30.
4	GX-B1378/22-F-23084	2023. 4. 11	所检项目合格	 A photograph showing a person in a laboratory or office environment, leaning over a desk and looking at a piece of equipment. The date stamp in the bottom right corner of the image is 2023/3/29.
5	GX-B1600/21-F-23005	2023. 4. 11	为可不注水煤层	
6	GX-B1600/21-F-23006	2023. 4. 14	为可不注水煤层	

7	GX-B1492/21-F-23003	2023. 4. 14	所检项目合格	
8	GX-B1377/22-F-23061	2023. 4. 14	所检项目合格	
9	GX-B1377/22-F-23062	2023. 4. 14.	所检项目合格	



10	GX-B1377/22-F-23063	2023. 4. 14	所检项目合格	
11	GX-B1377/22-F-23064	2023. 4. 14	所检项目合格	
12	GX-B1377/22-F-23065	2023. 4. 14	所检项目合格	

13	GX-B1377/22-F-23068	2023. 4. 14	所检项目合格	
14	GX-B1377/22-F-23069	2023. 4. 14	所检项目合格	
15	GX-B1377/22-F-23070	2023. 4. 14	所检项目合格	

16	GX-B1377/22-F-23071	2023. 4. 14	所检项目合格	
17	GX-B1377/22-F-23072	2023. 4. 14	所检项目合格	
18	GX-B1377/22-F-23073	2023. 4. 14	所检项目合格	

19	GX-B1377/22-F-23074	2023. 4. 14	所检项目合格	
20	GX-B1377/22-F-23075	2023. 4. 14	所检项目合格	
21	GX-B1377/22-F-23076	2023. 4. 14	所检项目合格	

22	GX-B1377/22-F-23077	2023. 4. 14	所检项目合格		
23	GX-B1377/22-F-23078	2023. 4. 14	所检项目合格		
24	GX-B1377/22-F-23079	2023. 4. 14	所检项目合格		

25	GX-B1377/22-F-23080	2023. 4. 14	所检项目合格		
26	GX-B1377/22-F-23081	2023. 4. 14	所检项目合格		
27	GX-B1378/22-F-23091	2023. 4. 12	所检项目合格		

28	GX-B1378/22-F-23087	2023. 4. 14	所检项目合格		
29	GX-B1378/22-F-23088	2023. 4. 14	所检项目合格		
30	GX-B1378/22-F-23086	2023. 4. 14	所检项目合格		

31	GX-B1378/22-F-23093~F-23094	2023. 4. 12	所检项目合格		
32	GX-B1489/22-F-23006	2023. 4. 14	所检项目合格		
33	GX-B1377/22-F-23082	2023. 4. 14	所检项目合格		

34	GX-B1377/22-F-23083	2023. 4. 14	所检项目合格		
35	GX-B1378/22-F-23092	2023. 4. 14	所检项目合格		
36	GX-B1378/22-F-23085	2023. 4. 14	所检项目合格		

37	GX-B1378/22-F-23095~F-23097	2023. 4. 12	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a dark jacket and a face mask, while the other is in a grey jacket. They are standing in front of a biosafety cabinet. The person in the grey jacket is operating the cabinet. A date stamp '2023/4/5' is visible in the bottom right corner of the image.
38	GX-B1378/22-F-23098	2023. 4. 12	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a dark jacket and a face mask, while the other is in a grey jacket. They are standing in front of a biosafety cabinet. The person in the grey jacket is operating the cabinet. A date stamp '2023/4/5' is visible in the bottom right corner of the image.
39	GX-B1378/22-F-23099	2023. 4. 12	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a dark jacket and a face mask, while the other is in a grey jacket. They are standing in front of a biosafety cabinet. The person in the grey jacket is operating the cabinet. A date stamp '2023/4/6' is visible in the bottom right corner of the image.

40	GX-B1378/22-F-23100	2023. 4. 12	所检项目合格	
41	GX-B1378/22-F-23103	2023. 4. 12	所检项目合格	
42	GX-B1377/22-F-23084	2023. 4. 14	所检项目合格	

43	GX-B1377/22-F-23085	2023. 4. 14	所检项目合格	 A photograph of a laboratory setting. Two individuals are working at a workstation with various pieces of equipment, including a computer monitor and a large white machine. A biohazard warning sign is visible on the wall. The date '2023/4/3' is printed in the bottom right corner of the image.
44	GX-B1377/22-F-23086	2023. 4. 14	所检项目合格	 A photograph of a laboratory setting, similar to the first row. Two individuals are working at a workstation with various pieces of equipment. A biohazard warning sign is visible on the wall. The date '2023/4/3' is printed in the bottom right corner of the image.
45	GX-B1377/22-F-23087	2023. 4. 14	所检项目合格	 A close-up photograph of a person wearing a blue lab coat and white gloves, working at a workstation in a laboratory. The person is focused on a task involving a piece of equipment. The date '2023/4/3' is printed in the bottom right corner of the image.

46	GX-B1377/22-F-23088	2023. 4. 14	所检项目合格	
47	GX-B1377/22-F-23089	2023. 4. 14	所检项目合格	
48	GX-B1377/22-F-23090	2023. 4. 14	所检项目合格	

49	GX-B1377/22-F-23091	2023. 4. 14	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a white lab coat and is looking down at something on a table. The other person is wearing a blue jacket and is standing next to them. There are various pieces of laboratory equipment, including what looks like a microscope and some containers, on the table. A date stamp '2023/4/14' is visible in the bottom right corner of the photo.
50	GX-B1377/22-F-23092	2023. 4. 14	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a white lab coat and is looking down at something on a table. The other person is wearing a blue jacket and is standing next to them. There are various pieces of laboratory equipment, including what looks like a microscope and some containers, on the table. A date stamp '2023/4/4' is visible in the bottom right corner of the photo.
51	GX-B1378/22-F-23089	2023. 4. 12	所检项目合格	 A photograph showing two individuals in a laboratory. One person is wearing a white lab coat and is looking down at something on a table. The other person is wearing a blue jacket and is standing next to them. There are various pieces of laboratory equipment, including what looks like a microscope and some containers, on the table. A date stamp '2023/4/30' is visible in the bottom right corner of the photo.

52	GX-B1378/22-F-23090	2023. 4. 12	所检项目合格	
53	GX-B1501/21-F-23005	2023. 4. 14	煤尘具有爆炸性	
54	GX-B1502/21-F-23005	2023. 4. 14	II类, 自燃	