





序号	报告编号	发布日期	结论	影像资料
112	GX-B1308/21-1-23022	2023. 5. 12	所检项目合格	
113	GX-B1499/21-1-23052	2023. 5. 12	所检项目合格	

114	GX-B1499/21-1-23053	2023. 5. 12	所检项目合格	
115	GX-B1499/21-1-23054	2023. 5. 12	所检项目合格	

116	GX-B1517/20-1-23017	2023. 5. 15	所检项目合格	
117	GX-B1517/20-1-23018	2023. 5. 15	所检项目合格	


118	GX-B1359/21-1-23060~23062	2023. 5. 16	所检项目合格	
119	GX-B1359/21-1-23063	2023. 5. 16	所检项目合格	



120	GX-B1359/21-1-23064~23065	2023. 5. 16	所检项目合格			
121	GX-B1359/21-1-23066-23067	2023. 5. 16	所检项目合格			

122	GX-B1359/21-1-23068	2023. 5. 16	所检项目合格	 <p>2023/3/2</p>
123	GX-B1359/21-1-23069	2023. 5. 16	所检项目合格	 <p>2023/3/3</p>

124	GX-B1359/21-1-23070~23071	2023. 5. 16	所检项目合格	
125	GX-B1359/21-1-23072~23073	2023. 5. 16	所检项目合格	

126	GX-B1359/21-1-23074~23075	2023. 5. 16	所检项目合格			
127	GX-B1359/21-1-23076~23078	2023. 5. 16	所检项目合格			

128	GX-B1359/21-1-23079~23080	2023. 5. 16	所检项目合格	
129	GX-B1359/21-1-23081~23082	2023. 5. 16	所检项目合格	

130	GX-B1359/21-1-23083~23084	2023. 5. 16	所检项目合格			
131	GX-B1359/21-1-23085~23087	2023. 5. 16	所检项目合格			

132	GX-B1359/21-1-23088~23089	2023. 5. 16	所检项目合格	
133	GX-B1359/21-1-23090~23092	2023. 5. 17	所检项目合格	

134	GX-B1329/21-1-23025~23036	2023/5/17	本次共检氧化锌避雷器12组，12组所检项目合格。	
135	GX-B1312/20-1-23283~23287	2023/5/17	本次共检电力变压器5台，5台所检项目合格。	
136	GX-B1312/20-1-23288~23295	2023/5/17	本次共检电力变压器8台，8台所检项目合格。	

137	GX-B1323/21-1-23138~23145	2023/5/17	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。	
138	GX-B1314/21-1-23008~23018	2023/5/17	本次共检煤矿在用干式电抗器11台，11台煤矿在用干式电抗器所检项目合格。	
139	GX-B1321/20-1-23532~23542	2023/5/17	本次共检电力电缆11条，11条电力电缆所检项目合格。	

140	GX-B1321/20-1-23524~23531	2023/5/17	本次共检电力电缆8条，8条电力电缆所检项目合格。	
141	GX-B1332/21-1-23025~23048	2023/5/17	本次共检电力电容器24台，24台所检项目合格。	

142	GX-B1495/20-1-23877~23893	2023/5/17	本次共检高压开关设备17台，17台高压开关设备所检项目合格。	
143	GX-B1495/20-1-23894~23907	2023/5/17	本次共检高压开关设备14台，14台高压开关设备所检项目合格。	

144	GX-B1350/21-1-23018	2023. 5. 18	所检项目合格	 A man wearing a blue short-sleeved shirt, black pants, and a white face mask is kneeling on a concrete surface. He is working on a piece of electrical equipment, possibly a meter or a small transformer, which is mounted on a concrete wall. There are some wires and tools scattered around him. A yellow date stamp '2023/04/28' is visible in the bottom left corner of the photo.
145	GX-B1329/21-1-23024	2023. 5. 18	所检项目合格	 A man wearing a blue short-sleeved shirt, black pants, and a white face mask is kneeling inside a narrow, enclosed space, likely an electrical cabinet or a small room. He is working on a piece of electrical equipment on the floor. There are various tools, including a pair of green gloves, and some cables scattered around him. A yellow date stamp '2023/04/28' is visible in the bottom left corner of the photo.

146	GX-B1313/21-1-23057	2023. 5. 18	所检项目合格	
147	GX-B1308/21-1-23023	2023. 5. 17	所检项目合格	

148	GX-B1499/21-1-23055	2023. 5. 17	所检项目合格	
149	GX-B1499/21-1-23056	2023. 5. 17	所检项目合格	

150	GX-B1499/21-1-23057	2023. 5. 17	所检项目合格	
151	GX-B1559/22-1-23011	2023. 5. 18	所检项目合格	

152	GX-B1559/22-1-23012	2023. 5. 18	所检项目合格	
153	GX-B1559/22-1-23013	2023. 5. 18	所检项目合格	

154	GX-B1559/22-1-23014	2023. 5. 18	所检项目合格	
155	GX-B1559/22-1-23015	2023. 5. 18	所检项目合格	

156	GX-B1559/22-1-23016	2023. 5. 18	所检项目合格	
157	GX-B1303/21-1-23005	2023/5/18	综合判定：合格	