





序号	报告编号	发布日期	结论	影像资料
115	GX-B1310/21-2-23068	2023. 5. 12	符合标准要求	
116	GX-B1427/21-2-23068	2023. 5. 12	符合标准要求	
117	GX-B1324/21-2-23005	45058	本次共检验三相交流电动机1台，1台三相交流电动机所检项目合格。	
118	GX-B1548/20-2-23002	2023. 5. 11	所检项目合格。	

119	GX-B1548/20-2-23003	2023. 5. 11	所检项目合格。	
120	GX-B1548/20-2-23004	2023. 5. 11	所检项目合格。	
121	GX-B1548/20-2-23005	2023. 5. 11	所检项目合格。	
122	GX-B1548/20-2-23006	2023. 5. 11	所检项目合格。	


123	GX-B1548/20-2-23007	2023. 5. 11	所检项目合格。	
124	GX-B1548/20-2-23008	2023. 5. 11	所检项目合格。	
125	GX-B1548/20-2-23009	2023. 5. 11	所检项目合格。	
126	GX-B1548/20-2-23011	2023. 5. 11	所检项目合格。	

127	GX-B1548/20-2-23012	2023. 5. 11	所检项目合格。	
128	GX-B1303/21-2-23002	2023. 5. 14	综合判定：合格	
129	GX-B1495/20-2-23215~23230	2023/5/15	所检项目合格	
130	GX-B1495/20-2-23231~23243	2023/5/15	所检项目合格	

131	GX-B1495/20-2-23215~23232	2023/5/15	所检项目合格	
132	GX-B1495/20-2-23215~23233	2023/5/15	所检项目合格	
133	GX-B1495/20-2-23274~23294	2023/5/15	所检项目合格	
134	GX-B1329/21-2-23107~23108	2023. 5. 15	本次共检氧化锌避雷器2组，2组所检项目合格。	

135	GX-B1310/21-2-23056	2023. 5. 15	符合标准要求	
136	GX-B1310/21-2-23057	2023. 5. 15	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
137	GX-B1428/21-2-23057	2023. 5. 15	无缺陷痕迹显示	
138	GX-B1310/21-2-23058	2023. 5. 15	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

139	GX-B1428/21-2-23058	2023. 5. 15	无缺陷迹痕显示		
140	GX-B1310/21-2-23059	2023. 5. 15	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		
141	GX-B1428/21-2-23059	2023. 5. 15	无缺陷迹痕显示		
142	GX-B1310/21-2-23067	2023. 5. 15	符合标准要求		

143	GX-B1386/21-2-23001	2023. 5. 15	所检项目合格	
144	GX-B1300/20-2-23007	2023. 5. 15	综合判定：合格	
145	GX-B1300/20-2-23008	2023. 5. 15	综合判定：合格	
146	GX-B1305/21-2-23001	2023. 5. 15	综合判定：合格	

147	GX-B1304/21-2-23003	2023. 5. 14	综合判定：合格	
148	GX-B1313/21-2-23104~23114	2023. 5. 15	所检项目合格	
149	GX-B1495/20-2-23295~23308	2023. 5. 16	所检项目合格	
150	GX-B1495/20-2-23309~23322	2023. 5. 16	所检项目合格	




151	GX-B1416/22-2-23013	2023. 5. 16	综合判定：合格。	
152	GX-B1302/21-2-23004	2023. 5. 16	综合判定：合格。	
153	GX-B1548/20-2-23012	2023. 5. 16	所检项目合格。	

154	GX-B1548/20-2-23013	2023. 5. 16	所检项目合格。	
155	GX-B1310/21-2-23075	2023. 5. 16	符合标准要求。	
156	GX-B1427/21-2-23075	2023. 5. 16	符合标准要求。	
157	GX-B1310/21-2-23076	2023. 5. 16	符合标准要求。	

158	GX-B1310/21-2-23077	2023. 5. 16	符合标准要求。		
159	GX-B1427/21-2-23077	2023. 5. 16	符合标准要求。		
160	GX-B1380/20-2-23005	2023. 5. 16	所检项目合格。		
161	GX-B1310/21-2- 23094	2023. 5. 17	符合标准要求。		

162	GX-B1310/21-2- 23095	2023. 5. 17	符合标准要求。	 <p>A photograph showing the rear view of an orange bus parked on a paved area. A date stamp '2023/05/03' is visible in the bottom right corner of the image.</p>
163	GX-B1310/21-2- 23096	2023. 5. 17	符合标准要求。	 <p>A photograph showing a worker in a pink uniform kneeling and inspecting the side of an orange vehicle. A date stamp '2023/05/03' is visible in the bottom right corner of the image.</p>
164	GX-B1310/21-2- 23097	2023. 5. 17	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and dark clothing inspecting a yellow vehicle. A date stamp '2023.05.03' is visible in the bottom right corner of the image.</p>

165	GX-B1310/21-2- 23098	2023. 5. 17	符合标准要求。	
166	GX-B1310/21-2- 23099	2023. 5. 17	符合标准要求。	
167	GX-B1310/21-2- 23100	2023. 5. 17	符合标准要求。	

168	GX-B1428/21-2- 23085	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/01</p>
169	GX-B1428/21-2- 23086	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/01</p>
170	GX-B1428/21-2- 23087	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/01</p>

171	GX-B1428/21-2- 23088	2023. 5. 18	无缺陷迹痕显示。	 A photograph showing two workers in red protective suits and hard hats standing in a dark environment, inspecting a large, spherical, grid-like structure. The workers are holding flashlights. A timestamp '2023/05/01' is visible in the bottom right corner of the image.
172	GX-B1428/21-2- 23089	2023. 5. 18	无缺陷迹痕显示。	 A photograph of a worker in a red protective suit and hard hat standing in a dark environment, inspecting a grid-like structure. The worker is holding a flashlight. A timestamp '2023/05/01' is visible in the bottom right corner of the image.
173	GX-B1428/21-2- 23090	2023. 5. 18	无缺陷迹痕显示。	 A photograph of a worker in a red protective suit and hard hat standing in a dark environment, inspecting a dark area. The worker is holding a flashlight. A timestamp '2023/05/02' is visible in the bottom right corner of the image.

174	GX-B1428/21-2- 23091	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/02</p>
175	GX-B1428/21-2- 23092	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/02</p>
176	GX-B1428/21-2- 23093	2023. 5. 18	无缺陷迹痕显示。	 <p>2023/05/02</p>