


序号	报告编号	发布日期	结论	影像资料
118	GX-B1362/20-A-23175	2023/5/15	合格	
119	GX-B1362/20-A-23176	2023/5/15	合格	

序号	报告编号	发布日期	结论	影像资料
120	GX-B1362/20-A-23177	2023/5/15	合格	 A photograph showing two men in grey work uniforms operating a large piece of industrial machinery. The machine has a prominent circular gauge on its right side. The man in the foreground is looking at the machine, while the man in the background is also engaged with it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the image.
121	GX-B1362/20-A-23178	2023/5/15	合格	 A photograph showing two men in grey work uniforms operating a different piece of industrial machinery. The machine is more complex with various components and a control panel. The man in the foreground is focused on the machine, while the man in the background is also working on it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
122	GX-B1362/20-A-23179	2023/5/15	安全系数结果10.46, 其余所检项目合格	
123	GX-B1362/20-A-23180	2023/5/15	安全系数结果10.48, 其余所检项目合格	



序号	报告编号	发布日期	结论	影像资料
124	GX-B1362/20-A-23181	2023/5/15	所检项目合格	 A photograph showing two workers in a workshop. One worker is standing and looking at a document, while the other is leaning over a long, perforated metal component on a workbench, using a tool to inspect it. A yellow timestamp '2023/5/12' is visible in the bottom right corner of the image.
125	GX-B1362/20-A-23182	2023/5/15	所检项目合格	 A photograph showing two workers in a workshop. One worker is in the foreground, operating a large industrial machine. Another worker is visible in the background, also working. A yellow timestamp '2023/5/12' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
126	GX-B1362/20-A-23183	2023/5/15	所检项目合格	
127	GX-B1362/20-A-23184	2023/5/15	所检项目合格	


序号	报告编号	发布日期	结论	影像资料
128	GX-B1362/20-A-23185	2023/5/15	所检项目合格	
129	GX-B1362/20-A-23186	2023/5/18	合格	




序号	报告编号	发布日期	结论	影像资料
130	GX-B1362/20-A-23187	2023/5/18	合格	
131	GX-B1362/20-A-23188	2023/5/18	安全系数结果8.81，其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
132	GX-B1362/20-A-23189	2023/5/18	安全系数结果8.98, 其余所检项目合格	
133	GX-B1362/20-A-23190	2023/5/18	安全系数结果8.90, 其余所检项目合格	



序号	报告编号	发布日期	结论	影像资料
134	GX-B1362/20-A-23191	2023/5/18	安全系数结果11.95, 其余所检项目合格	
135	GX-B1362/20-A-23208	2023/5/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
136	GX-B1362/20-A-23192	2023/5/18	合格	
137	GX-B1362/20-A-23193	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1362/20-A-23194	2023/5/18	合格	
139	GX-B1362/20-A-23195	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1362/20-A-23196	2023/5/18	合格	
141	GX-B1362/20-A-23197	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1362/20-A-23198	2023/5/18	安全系数结果9.61,其余所检项目合格	