



序号	报告编号	发布日期	结论	影像资料
151	GX-B1495/20-Y-231103~231108	2023年5月23日	本次共检高压开关设备6台，6台高压开关设备所检项目合格。	
152	GX-B1506/18-Y-23001	2023年5月29日	所检项目合格。	



153	GX-B1506/18-Y-23002	2023年5月29日	所检项目合格。	
154	GX-B1506/18-Y-23003	2023年5月29日	所检项目合格。	

155	GX-B1506/18-Y-23004	2023年5月29日	所检项目合格。	
156	GX-B1352/21-Y-23143~23145	2023年5月29日	本次共检矿用防爆低压交流真空馈电开关3台,3台矿用防爆低压交流真空馈电开关所检项目合格。	

157	GX-B1404/20-Y-23011	2023年5月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
158	GX-B1404/20-Y-23012	2023年5月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	


159	GX-B1354/20-Y-23009	2023年5月29日	电网接地电容电流符合规定。	
160	GX-B1404/20-Y-23009	2023年5月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

161	GX-B1404/20-Y-23010	2023年5月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
162	GX-B1495/20-Y-231190~231203	2023年5月29日	本次共检高压开关设备14台，14台高压开关设备所检项目合格。 。	

163	GX-B1495/20-Y-231204~231213	2023年5月29日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。 。	
164	GX-B1495/20-Y-231225~231227	2023年5月29日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	

165	GX-B1329/21-Y-23154~23158	2023年5月29日	本次共检氧化锌避雷器5组，5组氧化锌避雷器所检项目合格。	
166	GX-B1547/20-Y-23239~23247	2023年5月29日	本次共检继电保护装置9台，9台继电保护装置所检项目合格。	





167	GX-B1495/20-Y-231219~231222	2023年5月29日	本次共检高压防爆开关设备4台，4台高压防爆开关设备所检项目合格。	
168	GX-B1495/20-Y-231214~231218	2023年5月29日	本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。	

169	GX-B1312/20-Y-23240~23242	2023年5月25日	本次共检电力变压器3台，3台电力变压器所检项目合格。	
170	GX-B1328/20-Y-23074	2023年5月30日	本次共检绝缘手套62只，62只绝缘手套合格。	

171	GX-B1328/20-Y-23075	2023年4月18日	本次共检绝缘鞋 36只，36只绝缘鞋合格。	
172	GX-B1328/20-Y-23076	2023年4月18日	本次共检携带式接地 和接地短路装置 4组，4组携带式接地 和接地短路装置合格。 。	

173	GX-B1300/20-Y-23004	2023年5月30日	综合判定：合格	 <p>A worker in a white uniform and red helmet is inspecting a large blue electrical component with red insulators. The worker is standing on a platform and looking at the component. The date 2023.5.14 is visible in the bottom right corner of the photo.</p>
174	GX-B1328/20-Y-23067	2023年5月30日	本次共检绝缘手套40只，40只绝缘手套合格。	 <p>A worker in a white uniform and red helmet is kneeling on the ground, inspecting equipment in an outdoor area. There are yellow buckets and other tools nearby. The date 2023.5.18 is visible in the bottom right corner of the photo.</p>

175	GX-B1328/20-Y-23068	2023年5月30日	本次共检绝缘鞋 40只，40只绝缘鞋合格。	
176	GX-B1499/21-Y-23072	2023年5月30日	所检项目合格。	

177	GX-B1499/21-Y-23073	2023年5月30日	所检项目合格。	 A photograph of an industrial worker in a blue uniform and red hard hat standing next to a large piece of machinery. A blue sign with the number '2' is visible in the upper left corner of the photo. The date '2023/5/29' is printed in yellow at the bottom right.
178	GX-B1499/21-Y-23074	2023年5月30日	所检项目合格。	 A photograph of an industrial worker in a blue uniform and red hard hat standing next to a large piece of machinery. A blue sign with the number '3' is visible in the upper left corner of the photo. The date '2023/5/29' is printed in yellow at the bottom right.

179	GX-B1499/21-Y-23075	2023年5月30日	所检项目合格。	 <p>A photograph showing a worker in a blue uniform and red helmet standing next to a complex industrial valve assembly. The assembly is primarily blue with yellow accents. A blue square label with the number '4' is visible on the upper part of the equipment. The worker is positioned on a metal platform. A yellow date stamp '2023/5/29' is located in the bottom right corner of the image.</p>
180	GX-B1499/21-Y-23076	2023年5月30日	所检项目合格。	 <p>A photograph showing a worker in a blue uniform and red helmet standing next to a complex industrial valve assembly. The assembly is primarily blue with yellow accents. A blue square label with the number '5' is visible on the upper part of the equipment. The worker is positioned on a metal platform. A yellow date stamp '2023/5/29' is located in the bottom right corner of the image.</p>

181	GX-B1499/21-Y-23077	2023年5月30日	所检项目合格。	 A photograph of industrial machinery, likely a pump or motor, with blue and yellow components. A blue sign with the number '6' is visible. The date '2023/5/29' is printed in the bottom right corner.
182	GX-B1499/21-Y-23078	2023年5月30日	所检项目合格。	 A photograph of industrial machinery, similar to the one in the first row, with blue and yellow components. A blue sign with the number '7' is visible. The date '2023/5/29' is printed in the bottom right corner.



183	GX-B1308/21-Y-23013	2023年5月30日	所检项目合格。	
184	GX-B1499/21-Y-23070	2023年5月30日	实测流量为 184.2m <sup>3</sup> /h。	

185	GX-B1499/21-Y-23071	2023年5月30日	实测流量为 179.2m <sup>3</sup> /h。	
186	GX-B1563/21-Y-23008	2023年5月30日	所检项目合格。	

187	GX-B1423/20-Y-233457	2023年5月31日	综合判定： 合格	
188	GX-B1423/20-Y-233458	2023年5月31日	综合判定： 合格	

189	GX-B1423/20-Y-233459	2023年5月31日	综合判定： 合格	
190	GX-B1539/22-Y-23135	2023. 5. 31	所检项目合格。	

191	GX-B1539/22-Y-23136	2023. 5. 31	所检项目合格。	 <p>A photograph of a yellow ZL50CN wheel loader parked on a paved surface. Two workers wearing hard hats and safety vests are standing in front of the machine. The date '2023/5/17' is visible in the bottom right corner of the image.</p>
192	GX-B1539/22-Y-23137	2023. 5. 31	所检项目合格。	 <p>A photograph of a yellow ZL50CN wheel loader parked on a paved surface. Two workers wearing hard hats and safety vests are standing in front of the machine. The date '2023/5/17' is visible in the bottom right corner of the image.</p>


193	GX-B1539/22-Y-23138	2023. 5. 31	所检项目合格。	
194	GX-B1539/22-Y-23139	2023. 5. 31	所检项目合格。	

195	GX-B1539/22-Y-23140	2023. 5. 31	所检项目合格。	
196	GX-B1539/22-Y-23141	2023. 5. 31	所检项目合格。	

197	GX-B1539/22-Y-23142	2023. 5. 31	所检项目合格。	
198	GX-B1539/22-Y-23143	2023. 5. 31	所检项目合格。	



199	GX-B1539/22-Y-23144	2023. 5. 31	所检项目合格。	
200	GX-B1539/22-Y-23145	2023. 5. 31	所检项目合格。	

201	GX-B1306/21-Y-23080	2023年5月31日	除无储气罐检验证书外，其余所检项目合格。	
202	GX-B1306/21-Y-23081	2023年5月31日	除无储气罐检验证书外，其余所检项目合格。	

203	GX-B1306/21-Y-23082	2023年5月31日	除无储气罐检验证书外，其余所检项目合格。	 <p>A worker wearing a red hard hat and a grey uniform is kneeling on the floor, inspecting a piece of equipment. The date stamp in the bottom right corner of the photo is 2023/5/16.</p>
204	GX-B1339/21-Y-23011	2023年5月31日	所检项目合格。	 <p>Two workers wearing red hard hats and grey uniforms are inspecting a large blue industrial machine. The date stamp in the bottom right corner of the photo is 2023/5/15.</p>

205	GX-B1339/21-Y-23012	2023年5月31日	所检项目合格。	
206	GX-B1339/21-Y-23013	2023年5月31日	所检项目合格。	

207	GX-B1339/21-Y-23014	2023年5月31日	所检项目合格。	
-----	---------------------	------------	---------	---