

序号	报告编号	发布日期	结论	影像资料
239	GX-B1520/6-23082	2023/7/11	综合判定合格	
240	GX-B1423/20-6-23706	2023/7/17	综合判定合格	
241	GX-B1423/20-6-23707	2023/7/17	综合判定合格	

242	GX-B1423/20-6-23708	2023/7/17	综合判定合格	 A photograph showing two workers in safety gear (hard hats and high-visibility vests) standing in front of a yellow construction vehicle. The worker on the left is wearing a red hard hat and a light blue shirt, while the worker on the right is wearing a yellow hard hat and a grey uniform. The vehicle has '23708' written on its side. A timestamp '2023 7 4' is visible in the bottom right corner of the photo.
243	GX-B1423/20-6-23709	2023/7/17	综合判定合格	 A photograph showing two workers in safety gear standing in front of a yellow construction vehicle. The worker on the left is wearing a yellow hard hat and a grey uniform, while the worker on the right is wearing a red hard hat and a light blue shirt. The vehicle has '23709' written on its side. A timestamp '2023 7 4' is visible in the bottom right corner of the photo.
244	GX-B1423/20-6-23710	2023/7/17	综合判定合格	 A photograph showing two workers in safety gear standing in front of a yellow construction vehicle. The worker on the left is wearing a yellow hard hat and a grey uniform, while the worker on the right is wearing a red hard hat and a light blue shirt. The vehicle has '23710' written on its side. A timestamp '2023 7 4' is visible in the bottom right corner of the photo.

245	GX-B1423/20-6-23711	2023/7/17	综合判定合格	
246	GX-B1423/20-6-23712	2023/7/17	综合判定合格	
247	GX-B1423/20-6-23713	2023/7/17	综合判定合格	

248	GX-B1517/20-6-23015	2023/7/18	综合判定合格	
249	GX-B1423/20-6-23721	2023/7/19	综合判定合格	
250	GX-B1423/20-6-23722	2023/7/19	综合判定合格	

251	GX-B1423/20-6-23723	2023/7/19	综合判定合格	
252	GX-B1423/20-6-23724	2023/7/19	综合判定合格	
253	GX-B1423/20-6-23725	2023/7/19	综合判定合格	

254	GX-B1423/20-6-23726	2023/7/19	综合判定合格	
255	GX-B1423/20-6-23727	2023/7/19	综合判定合格	
256	GX-B1423/20-6-23728	2023/7/19	综合判定合格	

257	GX-B1423/20-6-23729	2023/7/19	综合判定合格	 A photograph showing two men standing in front of a green HOWO truck. The man on the left is wearing a red hard hat and a light blue short-sleeved shirt. The man on the right is wearing a light blue short-sleeved shirt. The truck's license plate is visible and reads '甘 93374'. A date stamp '2023 7 19' is visible in the bottom right corner of the photo.
258	GX-B1423/20-6-23730	2023/7/19	综合判定合格	 A photograph showing two men standing in front of a green HOWO truck. The man on the left is wearing a red hard hat and a light blue short-sleeved shirt. The man on the right is wearing a black short-sleeved shirt. The truck's license plate is visible and reads '甘 93384'. A date stamp '2023 7 19' is visible in the bottom right corner of the photo.
259	GX-B1352/21-6-23424~23436	2023/7/19	所检项目合格	 A photograph showing a worker in a dark blue uniform with reflective stripes standing next to a piece of machinery. The worker is wearing a headlamp. The machinery has a control panel with various buttons and switches. A date stamp '2023 05 31' is visible in the bottom right corner of the photo.

260	GX-B1328/20-6-23106	2023/7/19	所检项目合格	
261	GX-B1328/20-6-23107	2023/7/19	所检项目合格	
262	GX-B1328/20-6-23108	2023/7/19	所检项目合格	

263	GX-B1352/21-6-23437~23442	2023/7/19	所检项目合格	
264	GX-B1352/21-6-23443~23447	2023/7/19	所检项目合格	
265	GX-B1313/21-6-23168~23171	2023/7/19	所检项目合格	

266	GX-B1521/20-6-23001	2023/7/19	所检项目合格	
267	GX-B1521/20-6-23002	2023/7/19	所检项目合格	
268	GX-B1521/20-6-23003	2023/7/19	所检项目合格	

269	GX-B1521/20-6-23004	2023/7/19	所检项目合格	
270	GX-B1521/20-6-23005	2023/7/19	所检项目合格	
271	GX-B1521/20-6-23006	2023/7/19	所检项目合格	