

序号	报告编号	发布日期	结论	影像资料
214	GX-B1300/20-1-23007	2023. 7. 21	综合判定：合格	
215	GX-B1517/20-1-23042	2023. 7. 24	综合判定：合格。	
216	GX-B1517/20-1-23043	2023. 7. 24	综合判定：合格。	



217	GX-B1517/20-1-23044	2023. 7. 24	综合判定：合格。	
218	GX-B1517/20-1-23045	2023. 7. 24	综合判定：合格。	
219	GX-B1517/20-1-23046	2023. 7. 24	综合判定：合格。	

220	GX-B1517/20-1-23047	2023. 7. 24	综合判定：合格。	
221	GX-B1339/21-1-23017	2023/7/27	所检项目合格。	
222	GX-B1339/21-1-23018	2023/7/27	所检项目合格。	

223	GX-B1313/21-1-23084~23085	2023. 7. 27	本次共检电力变压器2台，2台所检项目合格	
224	GX-B1415/22-1-23008	2023/7/31	综合判定：合格。	
225	GX-B1415/22-1-23009	2023/7/31	综合判定：合格。	

226	GX-B1415/22-1-23010	2023/7/31	综合判定：合格。	 A photograph showing two workers in orange safety suits and red helmets. One worker is pointing at a blue light fixture, while the other looks on. The scene is dimly lit, typical of an underground tunnel. A yellow timestamp '2023/06/16' is visible in the bottom right corner of the image.
227	GX-B1415/22-1-23011	2023/7/31	综合判定：合格。	 A photograph of two workers in orange safety suits and red helmets. One worker is pointing upwards, and the other is looking at a device. They are in a tunnel with concrete walls and overhead pipes. A yellow timestamp '2023/06/16' is visible in the bottom right corner of the image.
228	GX-B1415/22-1-23012	2023/7/31	综合判定：合格。	 A photograph showing two workers in orange safety suits and red helmets. They are standing in a tunnel with a curved track or conveyor system. One worker is pointing towards the track. A yellow timestamp '2023/06/16' is visible in the bottom right corner of the image.

229	GX-B1451/20-1-23511~23516	2023. 7. 31	本次共检高压开关设备6台，6台高压开关设备所检项目合格	
230	GX-B1313/21-1-23080~23082	2023. 7. 31	本次共检电力变压器3台，3台所检项目合格	
231	GX-B1313/21-1-23083	2023. 7. 31	所检项目合格	

232	GX-B1322/21-1-23176~23188	2023. 7. 31	本次共检验电力电缆 13条，13条所检项目 合格			
233	GX-B1451/20-1-23439~23460	2023. 7. 31	本次共检高压开关设备 22台，22台高压开 关设备所检项目合格			
234	GX-B1451/20-1-23461~23486	2023. 7. 31	本次共检高压开关设备 26台，26台高压开 关设备所检项目合格			

235	GX-B1451/20-1-23487~23504	2023. 7. 31	本次共检高压开关设备18台，18台高压开关设备所检项目合格	
236	GX-B1310/21-1-23093	2023. 7. 31	符合标准要求	

23045

