

序号	报告编号	发布日期	结论	影像资料
139	GX-B1568/22-B-230302~230303	2023. 7. 21	所检项目合格	
140	GX-B1568/22-B-230304~230305	2023. 7. 21	所检项目合格	
141	GX-B1568/22-B-230255~230262	2023. 7. 21	所检项目合格	

142	GX-B1372/22-B- 230605~230610	2023. 7. 21	所检项目合格	 <p>2023.6.23</p>	
143	GX-B1603/22-B-230047~230051	2023. 7. 21	所检项目合格	 <p>2023.6.24</p>	
144	GX-B1601/22-B-230173	2023. 7. 21	所检项目合格	 <p>2023.6.26</p>	

145	GX-B1372/22-B- 230611~230619	2023. 7. 21	所检项目合格		
146	GX-B1372/22-B- 230620~230628	2023. 7. 21	所检项目合格		
147	GX-B1372/22-B- 230629~230636	2023. 7. 21	所检项目合格		

148	GX-B1603/22-B-230052~230057	2023. 7. 21	所检项目合格			
149	GX-B1568/22-B-230263~230264	2023. 7. 21	所检项目合格			
150	GX-B1601/22-B-230174	2023. 7. 21	所检项目合格			

151	GX-B1372/22-B- 230638~230642	2023. 7. 21	所检项目合格	 <p>2023.6.30</p>	
152	GX-B1568/22-B-230240	2023. 7. 21	所检项目合格	 <p>2023.6.27</p>	
153	GX-B1475/22-B- 230118	2023. 7. 21	所检项目合格	 <p>2023.7.1</p>	

154	GX-B1475/22-B- 230116~230117	2023. 7. 21	所检项目合格	
155	GX-B1568/22-B-230265~230267	2023. 7. 21	所检项目合格	
156	GX-B1601/22-B-230176~230177	2023. 7. 21	所检项目合格	

157	GX-B1373/21-B- 23223~23233	2023. 7. 21	所检项目合格			
158	GX-B1373/21-B- 23261~23269	2023. 7. 21	所检项目合格			
159	GX-B1374/22-B- 230347~230348	2023. 7. 21	所检项目合格			

160	GX-B1374/22-B- 230370~230373	2023. 7. 21	所检项目合格		
161	GX-B1592/21-B- 23045	2023.7.24	所检项目合格		
162	GX-B1373/21-B- 23210~23212	2023.7.24	所检项目合格		

163	GX-B1466/22-B- 23042~23046	2023.7.24	所检项目合格	
164	GX-B1465/22-B- 23067~23069	2023.7.24	所检项目合格	
165	GX-B1374/22-B- 230306~230315	2023.7.24	所检项目合格	

166	GX-B1540/20-B- 232240~232254	2023.7.24	所检项目合格	
167	GX-B1540/20-B- 232255~232263	2023.7.24	所检项目合格	
168	GX-B1540/20-B- 232284~232298	2023.7.24	所检项目合格	

169	GX-B1540/20-B- 232300~232314	2023.7.24	所检项目合格	 A photograph showing two male technicians in a laboratory. They are standing at a workstation with various pieces of equipment. One technician is leaning over a piece of equipment, while the other stands beside him. A yellow timestamp '2023.7.15' is visible in the bottom right corner of the image.
170	GX-B1540/20-B- 232315~232329	2023.7.24	所检项目合格	 A photograph showing two technicians, one male and one female, in a laboratory. They are working at a workstation with equipment. The male technician is leaning over a piece of equipment, and the female technician is standing next to him. A yellow timestamp '2023.7.14' is visible in the bottom right corner of the image.
171	GX-B1529/20-B- 23551~23555	2023.7.24	所检项目合格	 A photograph showing two technicians in a laboratory. They are working at a workstation with equipment. One technician is leaning over a piece of equipment, and the other is standing next to him. A yellow timestamp '2023.7.10' is visible in the bottom right corner of the image.

172	GX-B1568/22-B-230307~230312	2023.7.27	所检项目合格	
173	GX-B1568/22-B- 230241~230248	2023.7.27	所检项目合格	
174	GX-B1568/22-B- 230249~230254	2023.7.27	所检项目合格	

175	GX-B1568/22-B- 230268~230269	2023.7.27	所检项目合格			
176	GX-B1568/22-B- 230270~230278	2023.7.27	所检项目合格			
177	GX-B1568/22-B- 230307~230312	2023.7.27	所检项目合格			