







序号	报告编号	发布日期	结论	影像资料
15	GX-B1300/20-1-23012	2023/8/7	合格	
16	GX-B1300/20-1-23011	2023/8/7	合格	
17	GX-B1302/21-1-23006	2023. 8. 7	综合判定：合格	

18	GX-B1517/20-1-23050	2023. 8. 7	综合判定：合格	
19	GX-B1517/20-1-23051	2023. 8. 7	综合判定：合格	
20	GX-B1517/20-1-23052	2023. 8. 7	综合判定：合格	

21	GX-B1517/20-1-23053	2023. 8. 7	综合判定：合格	
22	GX-B1517/20-1-23054	2023. 8. 7	综合判定：合格	
23	GX-B1517/20-1-23055	2023. 8. 7	综合判定：合格	

24	GX-B1517/20-1-23056	2023. 8. 7	综合判定：合格		
25	GX-B1517/20-1-23057	2023. 8. 7	综合判定：合格		
26	GX-B1309/21-1-23020	2023. 8. 7	所检项目合格		

27	GX-B1500/21-1-23078	2023. 8. 7	综合判定：合格		
28	GX-B1500/21-1-23079	2023. 8. 7	综合判定：合格		
29	GX-B1500/21-1-23080	2023. 8. 7	综合判定：合格		

30	GX-B1309/21-1-23021	2023. 8. 7	所检项目合格			
31	GX-B1500/21-1-23081	2023. 8. 7	综合判定：合格			
32	GX-B1500/21-1-23082	2023. 8. 7	综合判定：合格			

33	GX-B1500/21-1-23083	2023. 8. 7	综合判定：合格		
34	GX-B1309/21-1-23022	2023. 8. 7	所检项目合格		
35	GX-B1500/21-1-23084	2023. 8. 7	综合判定：合格		

36	GX-B1500/21-1-23085	2023. 8. 7	综合判定：合格	
37	GX-B1500/21-1-23086	2023. 8. 7	综合判定：合格	
38	GX-B1310/21-1-23092	2023. 8. 7	符合标准要求	

39	GX-B1310/21-1- 23094	2023. 8. 7	符合标准要求	
40	GX-B1310/21-1- 23095	2023. 8. 7	符合标准要求	
41	GX-B1310/21-1- 23096	2023. 8. 7	符合标准要求	

42	GX-B1310/21-1- 23097	2023. 8. 7	符合标准要求	
43	GX-B1310/21-1- 23098	2023. 8. 7	符合标准要求	
44	GX-B1310/21-1- 23099	2023. 8. 7	符合标准要求	

45	GX-B1310/21-1- 23100	2023. 8. 7	符合标准要求	
46	GX-B1428/21-1-23092	2023. 8. 7	无缺陷迹痕显示	
47	GX-B1404/20-1-23027	2023. 8. 7	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合</p> <p>GB/T14549-1993 《电能质量 公用电网谐波》要求</p>	

48	GX-B1404/20-1-23028	2023. 8. 7	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求</p>		
49	GX-B1404/20-1-23029	2023. 8. 7	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求</p>		
50	GX-B1404/20-1-23030	2023. 8. 7	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求</p>		

51	GX-B1404/20-1-23031	2023. 8. 7	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求	
52	GX-B1417/22-1-23104	2023. 8. 8	综合判定：合格	
53	GX-B1417/22-1-23105	2023. 8. 8	综合判定：合格	

54	GX-B1417/22-1-23106	2023. 8. 8	综合判定：合格	
55	GX-B1417/22-1-23107	2023. 8. 8	综合判定：合格	
56	GX-B1417/22-1-23108	2023. 8. 8	综合判定：合格	

57	GX-B1309/21-1-23023	2023. 8. 8	所检项目合格		
58	GX-B1500/21-1-23087	2023. 8. 8	综合判定：合格		
59	GX-B1500/21-1-23088	2023. 8. 8	综合判定：合格		

60	GX-B1500/21-1-23089	2023. 8. 8	综合判定：合格		
61	GX-B1309/21-1-23024	2023. 8. 8	所检项目合格		
62	GX-B1500/21-1-23090	2023. 8. 8	综合判定：合格		




63	GX-B1500/21-1-23091	2023. 8. 8	综合判定：合格	 A worker in an orange safety vest and white hard hat stands next to a large green industrial machine. The date 2023.06.25 is visible in the bottom right corner of the photo.
64	GX-B1500/21-1-23092	2023. 8. 8	综合判定：合格	 A worker in an orange safety vest and white hard hat is kneeling next to a large green industrial machine. The date 2023.06.25 is visible in the bottom right corner of the photo.
65	GX-B1500/21-1-23093	2023. 8. 8	综合判定：合格	 A worker in an orange safety vest and white hard hat is sitting on a metal ladder next to a large green industrial machine. The date 2023.06.25 is visible in the bottom right corner of the photo.

66	GX-B1309/21-1-23025	2023. 8. 8	所检项目合格		 <p>2023.06.20</p>
67	GX-B1500/21-1-23094	2023. 8. 8	综合判定：合格		 <p>2023.06.20</p>
68	GX-B1500/21-1-23095	2023. 8. 8	综合判定：合格		 <p>2023.06.20</p>

69	GX-B1500/21-1-23096	2023. 8. 8	综合判定：合格		
70	GX-B1309/21-1-23026	2023. 8. 8	所检项目合格		
71	GX-B1500/21-1-23097	2023. 8. 8	综合判定：合格		

72	GX-B1500/21-1-23098	2023. 8. 8	综合判定：合格		
73	GX-B1500/21-1-23099	2023. 8. 8	综合判定：合格		
74	GX-B1309/21-1-23027	2023. 8. 8	所检项目合格		

75	<u>GX-B1500/21-1-23100</u>	2023. 8. 8	综合判定：合格		
76	<u>GX-B1500/21-1-23101</u>	2023. 8. 8	综合判定：合格		
77	<u>GX-B1500/21-1-23102</u>	2023. 8. 8	综合判定：合格		




78	GX-B1500/21-1-23103	2023. 8. 8	综合判定：合格	
79	GX-B1313/21-1-23086~23088	2023. 8. 8	本次共检电力变压器3台，3台电力变压器所检项目合格	
80	GX-B1313/21-1-23089~23094	2023. 8. 8	本次共检电力变压器6台，6台电力变压器所检项目合格	

81	GX-B1322/21-1-23189~23195	2023. 8. 8	本次共检验电力 电缆7条，7条所 检项目合格	
82	GX-B1322/21-1-23196~23202	2023. 8. 8	本次共检验电力 电缆7条，7条所 检项目合格	
83	GX-B1322/21-1-23203~23207	2023. 8. 8	本次共检验电力 电缆5条，5条所 检项目合格	

84	GX-B1451/20-1-23517~23540	2023. 8. 8	本次共检高压开关设备24台，24台高压开关设备所检项目合格		
85	GX-B1451/20-1-23541~23559	2023. 8. 8	本次共检高压开关设备19台，19台高压开关设备所检项目合格		
86	GX-B1451/20-1-23560~23593	2023. 8. 8	本次共检高压开关设备34台，34台高压开关设备所检项目合格		

87	GX-B1451/20-1-23594~23622	2023. 8. 8	本次共检高压开关设备29台，29台高压开关设备所检项目合格			
88	GX-B1520/20-1-23026	2023. 8. 9	综合判定：合格			
89	GX-B1520/20-1-23027	2023. 8. 9	综合判定：合格			

90	GX-B1423/20-1-23380	2023/8/9	综合判定：合格	
91	GX-B1423/20-1-23381	2023/8/9	综合判定：合格	
92	GX-B1423/20-1-23382	2023/8/9	综合判定：合格	

93	GX-B1423/20-1-23383	2023/8/9	综合判定：合格	
94	GX-B1423/20-1-23384	2023/8/9	综合判定：合格	
95	GX-B1423/20-1-23385	2023/8/9	综合判定：合格	

96	GX-B1423/20-1-23386	2023/8/9	综合判定：合格	
97	GX-B1423/20-1-23387	2023/8/9	综合判定：合格	
98	GX-B1423/20-1-23388	2023/8/9	综合判定：合格	

99	GX-B1423/20-1-23389	2023/8/9	综合判定：合格	
100	GX-B1423/20-1-23390	2023/8/9	综合判定：合格	
101	GX-B1423/20-1-23391	2023/8/9	综合判定：合格	

102	GX-B1423/20-1-23392	2023/8/9	综合判定：合格	
103	GX-B1423/20-1-23393	2023/8/9	综合判定：合格	
104	GX-B1423/20-1-23394	2023/8/9	综合判定：合格	