

序号	报告编号	发布日期	结论	影像资料
325	GX-B1310/21-Y-23123	2023年8月9日	符合标准要求。 。	

326	GX-B1310/21-Y-23124	2023年8月9日	符合标准要求。 。	
-----	---------------------	-----------	--------------	---

327	GX-B1424/20-Y-23012	2023年8月9日	所检项目合格。 。	
-----	---------------------	-----------	--------------	---

328	GX-B1424/20-Y-23013	2023年8月9日	所检项目合格。 。	
329	GX-B1521/20-Y-23415	2023年8月9日	所检项目合格。 。	

330	GX-B1521/20-Y-23416	2023年8月9日	所检项目合格。 。	
331	GX-B1521/20-Y-23417	2023年8月9日	所检项目合格。 。	

332	GX-B1521/20-Y-23418	2023年8月9日	所检项目合格。 。	
333	GX-B1521/20-Y-23419	2023年8月9日	所检项目合格。 。	

334	GX-B1521/20-Y-23420	2023年8月9日	所检项目合格。 。	 A yellow Sany excavator is shown in operation at a construction site. The excavator's arm is raised, and it appears to be working on a pile of earth or rock. Several workers wearing hard hats and safety vests are visible in the background, observing the machine. The sky is blue with scattered white clouds. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the image.
335	GX-B1521/20-Y-23421	2023年8月9日	所检项目合格。 。	 A yellow excavator is shown working on a rocky construction site. The excavator is positioned on a pile of rocks and debris, with its arm extended. Workers in safety gear are visible in the background. The sky is blue with white clouds. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the image.

336	GX-B1521/20-Y-23422	2023年8月9日	所检项目合格。 。	
337	GX-B1539/22-Y-23178	2023年8月9日	所检项目合格。 。	

338	GX-B1539/22-Y-23179	2023年8月9日	所检项目合格。 。	
339	GX-B1539/22-Y-23180	2023年8月9日	所检项目合格。 。	

340	GX-B1539/22-Y-23181	2023年8月9日	所检项目合格。 。	
341	GX-B1539/22-Y-23182	2023年8月9日	所检项目合格。 。	

342	GX-B1539/22-Y-23183	2023年8月9日	所检项目合格。 。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers wearing safety vests and hard hats are standing next to the loader. A yellow timestamp '2023/7/16' is visible in the bottom right corner of the photo.
343	GX-B1539/22-Y-23184	2023年8月9日	所检项目合格。 。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers wearing safety vests and hard hats are standing next to the loader. A yellow timestamp '2023/7/16' is visible in the bottom right corner of the photo.

344	GX-B1539/22-Y-23185	2023年8月9日	所检项目合格。 。	
345	GX-B1539/22-Y-23186	2023年8月9日	所检项目合格。 。	

346	GX-B1539/22-Y-23187	2023年8月9日	所检项目合格。 。	
347	GX-B1539/22-Y-23188	2023年8月9日	所检项目合格。 。	

348	GX-B1539/22-Y-23189	2023年8月9日	所检项目合格。 。	
349	GX-B1539/22-Y-23190	2023年8月9日	所检项目合格。 。	

350	GX-B1539/22-Y-23191	2023年8月9日	所检项目合格。 。	
351	GX-B1521/20-Y-23423	2023年8月10日	所检项目合格。 。	

352	GX-B1521/20-Y-23424	2023年8月10日	所检项目合格。 。	
353	GX-B1521/20-Y-23425	2023年8月10日	所检项目合格。 。	

354	GX-B1521/20-Y-23426	2023年8月10日	所检项目合格。 。	
355	GX-B1521/20-Y-23427	2023年8月10日	所检项目合格。 。	

356	GX-B1521/20-Y-23428	2023年8月10日	所检项目合格。 。	 A photograph of a red Hitachi excavator with a large bucket, parked on a dirt surface. A person in a yellow safety vest is standing next to the machine. The date stamp '2023/7/16' is visible in the bottom right corner of the image.
357	GX-B1521/20-Y-23429	2023年8月10日	所检项目合格。 。	 A photograph of a red Hitachi excavator with a large bucket, parked on a dirt surface. A person in a yellow safety vest is standing next to the machine. The date stamp '2023/7/16' is visible in the bottom right corner of the image.

358	GX-B1521/20-Y-23430	2023年8月10日	所检项目合格。 。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and a worker in a yellow safety vest is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/7/16' is visible in the bottom right corner of the image.
359	GX-B1521/20-Y-23431	2023年8月10日	所检项目合格。 。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and a worker in a yellow safety vest is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/7/16' is visible in the bottom right corner of the image.

360	GX-B1521/20-Y-23432	2023年8月10日	所检项目合格。 。	 A yellow Hitachi excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its bucket is lowered. A person in a high-visibility vest is standing near the excavator. The background shows a clear blue sky and some distant hills. A yellow timestamp "2023/8/17" is visible in the bottom right corner of the image.
361	GX-B1521/20-Y-23433	2023年8月10日	所检项目合格。 。	 A yellow Sany excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its bucket is lowered. A person in a high-visibility vest is standing near the excavator. The background shows a clear blue sky and some distant hills. A yellow timestamp "2023/8/17" is visible in the bottom right corner of the image.

362	GX-B1521/20-Y-23434	2023年8月10日	所检项目合格。 。	
363	GX-B1521/20-Y-23435	2023年8月10日	所检项目合格。 。	

364	GX-B1521/20-Y-23436	2023年8月10日	所检项目合格。 。	
365	GX-B1521/20-Y-23437	2023年8月10日	所检项目合格。 。	

366	GX-B1521/20-Y-23438	2023年8月10日	所检项目合格。 。	
367	GX-B1521/20-Y-23439	2023年8月10日	所检项目合格。 。	

368	GX-B1521/20-Y-23440	2023年8月10日	所检项目合格。 。	
369	GX-B1521/20-Y-23446	2023年8月10日	所检项目合格。 。	

370	GX-B1521/20-Y-23447	2023年8月10日	所检项目合格。 。	 A photograph of an orange Hitachi excavator at a construction site. A worker in a yellow safety vest and red hard hat stands next to the machine. The date stamp '2023/7/19' is visible in the bottom right corner of the image.
371	GX-B1521/20-Y-23448	2023年8月10日	所检项目合格。 。	 A photograph of an orange Hitachi excavator at a construction site. A worker in a yellow safety vest and red hard hat stands next to the machine. The date stamp '2023/7/19' is visible in the bottom right corner of the image.

372	GX-B1521/20-Y-23449	2023年8月10日	所检项目合格。 。	
373	GX-B1521/20-Y-23450	2023年8月10日	所检项目合格。 。	

374	GX-B1521/20-Y-23445	2023年8月10日	所检项目合格。 。	
-----	---------------------	------------	--------------	---

375	GX-B1539/22-Y-23195	2023年8月10日	所检项目合格。 。	
-----	---------------------	------------	--------------	---

376	GX-B1563/21-Y-23024	2023年8月10日	所检项目合格。 。	
-----	---------------------	------------	--------------	---

377	GX-B1563/21-Y-23025	2023年8月10日	所检项目合格。 。	
-----	---------------------	------------	--------------	---