





序号	报告编号	发布日期	结论	影像资料
16	GX-B1428/21-1-23131	2023/9/7	无缺陷迹痕显示	 A photograph showing a worker in an orange protective suit and red helmet standing on a concrete walkway next to a large, dark, rectangular structure, possibly a dam or spillway. The worker is looking towards the structure. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the image.
17	GX-B1428/21-1-23132	2023/9/7	无缺陷迹痕显示	 A photograph taken from an elevated position looking down into a large concrete structure. A worker in an orange protective suit and red helmet is visible, standing on a narrow ledge or platform. The structure has a curved, ribbed appearance. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the image.
18	GX-B1428/21-1-23133	2023/9/7	无缺陷迹痕显示	 A photograph showing a worker in an orange protective suit and red helmet standing on a narrow ledge or platform within a large concrete structure. The worker is looking towards the camera. The structure has a curved, ribbed appearance. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the image.

19	GX-B1428/21-1-23134	2023/9/7	无缺陷迹痕显示	
20	GX-B1423/20-1-23447	2023. 9. 7	综合判定：合格	
21	GX-B1423/20-1-23448	2023. 9. 7	综合判定：合格	
22	GX-B1423/20-1-23449	2023. 9. 7	综合判定：合格	

23	GX-B1534/20-1-23025	2023. 9. 8	所检项目合格	
24	GX-B1534/20-1-23026	2023. 9. 8	所检项目合格	
25	GX-B1423/20-1-23563	2023. 9. 8	综合判定：合格	
26	GX-B1423/20-1-23564	2023. 9. 8	综合判定：合格	





27	GX-B1423/20-1-23565	2023. 9. 8	综合判定：合格		
28	GX-B1423/20-1-23566	2023. 9. 8	综合判定：合格		
29	GX-B1423/20-1-23567	2023. 9. 8	综合判定：合格		
30	GX-B1423/20-1-23568	2023. 9. 8	综合判定：合格		

31	GX-B1423/20-1-23569	2023. 9. 8	综合判定：合格		
32	GX-B1423/20-1-23570	2023. 9. 8	综合判定：合格		
33	GX-B1423/20-1-23571	2023. 9. 8	综合判定：合格		
34	GX-B1423/20-1-23572	2023. 9. 8	综合判定：合格		

35	GX-B1423/20-1-23591	2023. 9. 8	综合判定：合格	 <p>2023.08.31</p>
36	GX-B1423/20-1-23592	2023. 9. 8	综合判定：合格	 <p>2023.08.31</p>
37	GX-B1423/20-1-23593	2023. 9. 8	综合判定：合格	 <p>2023.08.31</p>
38	GX-B1423/20-1-23594	2023. 9. 8	综合判定：合格	 <p>2023.08.31</p>

39	GX-B1423/20-1-23595	2023. 9. 8	综合判定：合格	
40	GX-B1423/20-1-23596	2023. 9. 8	综合判定：合格	
41	GX-B1423/20-1-23597	2023. 9. 8	综合判定：合格	
42	GX-B1423/20-1-23598	2023. 9. 8	综合判定：合格	

43	GX-B1423/20-1-23599	2023. 9. 8	综合判定：合格	
44	GX-B1423/20-1-23600	2023. 9. 8	综合判定：合格	
45	GX-B1423/20-1-23579	2023. 9. 8	综合判定：合格	
46	GX-B1423/20-1-23580	2023. 9. 8	综合判定：合格	

47	GX-B1423/20-1-23581	2023. 9. 8	综合判定：合格	
48	GX-B1423/20-1-23582	2023. 9. 8	综合判定：合格	
49	GX-B1423/20-1-23583	2023. 9. 8	综合判定：合格	
50	GX-B1423/20-1-23584	2023. 9. 8	综合判定：合格	

51	GX-B1423/20-1-23585	2023. 9. 8	综合判定：合格	
52	GX-B1423/20-1-23586	2023. 9. 8	综合判定：合格	
53	GX-B1423/20-1-23587	2023. 9. 8	综合判定：合格	
54	GX-B1423/20-1-23588	2023. 9. 8	综合判定：合格	

55	GX-B1328/20-1-23087	2023. 9. 8	本次共检绝缘手套80只，80只所检项目合格	
56	GX-B1328/20-1-23088	2023. 9. 8	本次共检绝缘鞋80只，80只所检项目合格	
57	GX-B1328/20-1-23089	2023. 9. 8	本次共检绝缘手套28只，28只绝缘手套所检项目合格	
58	GX-B1328/20-1-23090	2023. 9. 8	本次共检绝缘鞋28只，28只绝缘鞋所检项目合格	

59	GX-B1423/20-1-23543	2023. 9. 7	综合判定：合格	
60	GX-B1423/20-1-23544	2023. 9. 7	综合判定：合格	
61	GX-B1423/20-1-23545	2023. 9. 7	综合判定：合格	
62	GX-B1423/20-1-23546	2023. 9. 7	综合判定：合格	


63	GX-B1423/20-1-23547	2023. 9. 7	综合判定：合格	
64	GX-B1423/20-1-23548	2023. 9. 7	综合判定：合格	
65	GX-B1423/20-1-23549	2023. 9. 7	综合判定：合格	
66	GX-B1423/20-1-23550	2023. 9. 7	综合判定：合格	

67	GX-B1423/20-1-23551	2023. 9. 7	综合判定：合格	
68	GX-B1423/20-1-23552	2023. 9. 7	综合判定：合格	
69	GX-B1423/20-1-23553	2023. 9. 7	综合判定：合格	
70	GX-B1423/20-1-23554	2023. 9. 7	综合判定：合格	

71	GX-B1423/20-1-23555	2023. 9. 7	综合判定：合格		
72	GX-B1423/20-1-23556	2023. 9. 7	综合判定：合格		
73	GX-B1423/20-1-23557	2023. 9. 7	综合判定：合格		
74	GX-B1423/20-1-23558	2023. 9. 7	综合判定：合格		

75	GX-B1423/20-1-23559	2023. 9. 7	综合判定：合格		
76	GX-B1423/20-1-23560	2023. 9. 7	综合判定：合格		
77	GX-B1423/20-1-23561	2023. 9. 7	综合判定：合格		
78	GX-B1423/20-1-23562	2023. 9. 7	综合判定：合格		

79	GX-B1404/20-1-23032	2023. 9. 8	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
80	GX-B1404/20-1-23033	2023. 9. 8	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1994 《电能质量 公用电网谐波》要求。	
81	GX-B1404/20-1-23034	2023. 9. 8	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1995 《电能质量 公用电网谐波》要求。	
82	GX-B1404/20-1-23035	2023. 9. 8	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1996 《电能质量 公用电网谐波》要求。	

83	GX-B1354/20-1-23008	2023. 9. 8	电网接地电容电流符合规定 。 。	
----	---------------------	------------	---------------------	---