







序号	报告编号	发布日期	结论	影像资料
11	GX-B1517/20-7-23066	2023. 9. 14	综合判定：合格	
12	GX-B1517/20-7-23067	2023. 9. 14	综合判定：合格	
13	GX-B1517/20-7-23068	2023. 9. 14	综合判定：合格	

14	GX-B1415/22-7-23010	2023. 9. 15	综合判定：合格。			
15	GX-B1310/21-7-23089	2023. 9. 18	符合标准要求			
16	GX-B1310/21-7-23090	2023. 9. 18	符合标准要求			
17	GX-B1310/21-7-23091	2023. 9. 18	符合标准要求			

18	GX-B1310/21-7-23092	2023. 9. 18	符合标准要求		
19	GX-B1424/20-7-23030	2023. 9. 18	依据NB/T 10176-2019单轨吊车综合判定合格。		
20	GX-B1424/20-7-23031	2023. 9. 18	依据NB/T 10176-2019单轨吊车综合判定合格。		
21	GX-B1424/20-7-23032	2023. 9. 18	依据NB/T 10176-2019单轨吊车综合判定合格。		

22	GX-B1424/20-7-23033	2023. 9. 18	依据NB/T 10176-2019单轨吊车综合判定合格。	
23	GX-B1404/20-7-23177	2023. 9. 19	所检电网5次谐波电流不符合GB/T 14549-1993 《电能质量 公用电网谐波》要求限值。其余各项符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
24	GX-B1404/20-7-23178	2023. 9. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	