


序号	报告编号	发布日期	结论	影像资料
1	GX-B1367/22-A-23093	2023/10/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2	GX-B1363/22-A-23422	2023/10/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1363/22-A-23421	2023/10/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
4	GX-B1363/22-A-23420	2023/10/8	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
5	GX-B1363/22-A-23410	2023/10/8	所检项目合格。	 A photograph showing two technicians in light blue work shirts inspecting a large, rusted industrial furnace. One technician is wearing blue gloves. The furnace has a large white chimney pipe on top. A date stamp '2023/09/28' is visible in the bottom right corner of the image.


序号	报告编号	发布日期	结论	影像资料
6	GX-B1363/22-A-23423	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1363/22-A-23424	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1363/22-A-23425	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
9	GX-B1363/22-A-23439	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1463/22-A-23005	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1463/22-A-23004	2023/10/8	所检项目合格。	 A photograph showing two individuals in white lab coats working at a desk. They are looking down at documents or equipment on the desk. The desk has a blue file organizer with several folders. A date stamp '2023/09/26' is visible in the bottom right corner of the image. The background shows a window with yellow curtains.

序号	报告编号	发布日期	结论	影像资料
12	GX-B1367/22-A-23094	2023/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1363/22-A-23427	2023/10/9	全厚度拉伸强度为1610N/mm，拉伸伸长率为21%，其余所检项目合格。	