

序号	报告编号	发布日期	结论	影像资料
16	GX-B1534/20-1-23038	2023. 11. 20	所检项目合格	
17	GX-B1534/20-1-23039	2023. 11. 20	所检项目合格	

18	GX-B1534/20-1-23040	2023. 11. 20	所检项目合格			
19	GX-B1534/20-1-23041	2023. 11. 20	所检项目合格			

20	GX-B1539/22-1-23003	2023/11/17	所检项目合格	
21	GX-B1423/20-1-23720	2023/11/20	综合判定：合格	

22	GX-B1423/20-1-23721	2023/11/20	综合判定：合格	
23	GX-B1423/20-1-23722	2023/11/20	综合判定：合格	

24	GX-B1423/20-1-23723	2023/11/20	综合判定：合格	 A photograph of a yellow MT860 truck at a construction site. Two workers in red hard hats and work clothes stand in front of the truck. A vertical yellow timestamp '2023/11/13' is visible on the left side of the image.
25	GX-B1423/20-1-23724	2023/11/20	综合判定：合格	 A photograph of a yellow MT865 truck at a construction site. Two workers in red hard hats and work clothes stand in front of the truck. A vertical yellow timestamp '2023/11/13' is visible on the left side of the image.

26	GX-B1423/20-1-23725	2023/11/20	综合判定：合格	
27	GX-B1423/20-1-23726	2023/11/20	综合判定：合格	

28	GX-B1423/20-1-23727	2023/11/20	综合判定：合格	
29	GX-B1423/20-1-23728	2023/11/20	综合判定：合格	

30	GX-B1423/20-1-23729	2023/11/20	综合判定：合格	
----	---------------------	------------	---------	-------------------------------------------------------------------------------------

23045

