






序号	报告编号	发布日期	结论	影像资料
1	GX-B1377/22-F-23302	2023.12.7	所检项目合格	
2	GX-B1377/22-F-23303	2023.12.7	所检项目合格	

3	GX-B1377/22-F-23305	2023.12.7	所检项目合格	
4	GX-B1377/22-F-23306	2023.12.7	所检项目合格	

5	GX-B1492/21-F-23026		所检项目合格	
6	GX-B1492/21-F-23028	2023. 12. 7	所检项目合格	
7	GX-B1492/21-F-23027	2023. 12. 7	所检项目合格	

8	GX-B1489/21-F- 23093	2023. 12. 7	所检项目合格	
9	GX-B1489/21-F- 23094	2023. 12. 7	所检项目合格	
10	GX-B1489/21-F- 23095	2023. 12. 7	所检项目合格	

11	GX-B1489/21-F-23091	2023.12.7	所检项目合格	 A photograph showing two laboratory workers in grey uniforms and masks. They are standing at a laboratory bench. On the bench, there is a blue water dispenser and a piece of laboratory equipment. The date '2023/11/27' is visible in the bottom right corner of the image.
12	GX-B1489/21-F-23092	2023.12.7	所检项目合格	 A photograph showing two laboratory workers in grey uniforms and masks. They are standing at a laboratory bench, looking at a large piece of laboratory equipment. The date '2023/11/27' is visible in the bottom right corner of the image.
13	GX-B1377/22-F-23298	2023.12.7	所检项目合格	 A photograph showing two laboratory workers. One is wearing a white lab coat and the other is wearing a grey uniform. They are standing at a laboratory bench with various pieces of laboratory equipment, including a large white machine and several bottles. The date '2023/11/27' is visible in the bottom right corner of the image.

14	GX-B1377/22-F-23299	2023. 12. 7	所检项目合格	 A photograph showing two female laboratory technicians in white lab coats and face masks. They are standing at a workstation with a large, light-colored piece of laboratory equipment. One technician is looking at the equipment while the other stands beside her. A white container with Chinese characters is on the counter. A small date stamp '2023/11/27' is visible in the bottom right corner of the photo.
15	GX-B1377/22-F-23300	2023. 12. 7	所检项目合格	 A photograph showing two female laboratory technicians in white lab coats and face masks. They are standing at a workstation with a large, light-colored piece of laboratory equipment. One technician is looking at the equipment while the other stands beside her. A small date stamp '2023/11/27' is visible in the bottom right corner of the photo.
16	GX-B1377/22-F-23301	2023. 12. 7	所检项目合格	 A photograph showing two female laboratory technicians in white lab coats and face masks. They are standing at a workstation with a large, light-colored piece of laboratory equipment. One technician is looking at the equipment while the other stands beside her. A small date stamp '2023/11/27' is visible in the bottom right corner of the photo.

17	GX-B1378/22-F-23249	2023. 12. 7	所检项目合格	
18	GX-B1378/22-F-23250	2023. 12. 7	所检项目合格	
19	GX-B1378/22-F-23251	2023. 12. 7	所检项目合格	

20	GX-B1378/22-F-23252	2023. 12. 7	所检项目合格	
21	GX-B1378/22-F-23253	2023. 12. 7	所检项目合格	
22	GX-B1378/22-F-23254~F-23255	2023. 12. 7	所检项目合格	

23	GX-B1378/22-F-23260	2023. 12. 7	所检项目合格	
24	GX-B1489/21-F-23096	2023. 12. 7	所检项目合格	
25	GX-B1489/21-F-23097	2023. 12. 7	所检项目合格	

26	GX-B1492/21-F-23029	2023. 12. 7	所检项目合格	
27	GX-B1378/22-F-23256	2023. 12. 7	所检项目合格	
28	GX-B1378/22-F-23257	2023. 12. 7	所检项目合格	

29	GX-B1378/22-F-23258	2023. 12. 7	所检项目合格	
30	GX-B1378/22-F-23259	2023. 12. 7	所检项目合格	