


序号	报告编号	发布日期	结论	影像资料
118	GX-B1321/20-Y-24002~24006	2024年1月24日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	

119	GX-B1321/20-Y-24007~24010	2024年1月24日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
120	GX-B1321/20-Y-24011~24018	2024年1月24日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	

121	GX-B1328/20-Y-24008	2024年1月24日	本次共检验电器 3支，3支验电器所检 项目合格。	
122	GX-B1328/20-Y-24009	2024年1月24日	所检项目合格。	

123	GX-B1328/20-Y-24010	2024年1月24日	本次共检绝缘杆 4支，4支绝缘杆所检 项目合格。	
124	GX-B1328/20-Y-24011	2024年1月26日	本次共检验电器 2支，2支验电器所检 项目合格。	

125	GX-B1328/20-Y-24012	2024年1月26日	本次共检验绝缘杆2支，2支绝缘杆所检项目合格。	
126	GX-B1539/22-Y-24004	2024年1月28日	所检项目合格。	

127	GX-B1539/22-Y-24005	2024年1月28日	所检项目合格。	
128	GX-B1539/22-Y-24006	2024年1月28日	所检项目合格。	

129	GX-B1539/22-Y-24007	2024年1月28日	所检项目合格。	
130	GX-B1521/20-Y-24023	2024年1月28日	所检项目合格。	

131	GX-B1521/20-Y-24024	2024年1月28日	所检项目合格。	
132	GX-B1521/20-Y-24025	2024年1月28日	所检项目合格。	

133	GX-B1521/20-Y-24026	2024年1月28日	所检项目合格。	
134	GX-B1521/20-Y-24027	2024年1月28日	所检项目合格。	

135	GX-B1521/20-Y-24028	2024年1月28日	所检项目合格。	 A yellow CAT excavator is shown in an outdoor setting, possibly a construction or mining site. The excavator is positioned on a dark surface, and its arm is raised. Two workers in blue uniforms are standing near the base of the excavator. The background shows a clear blue sky and some distant structures. A yellow date stamp "2024/1/14" is visible in the bottom right corner of the image.
136	GX-B1521/20-Y-24029	2024年1月28日	所检项目合格。	 A yellow CAT excavator is shown in an outdoor setting, similar to the first image. The excavator is positioned on a dark surface, and its arm is raised. Two workers in blue uniforms are standing near the base of the excavator. The background shows a clear blue sky and some distant structures. A yellow date stamp "2024/1/14" is visible in the bottom right corner of the image.

137	GX-B1521/20-Y-24030	2024年1月28日	所检项目合格。	
138	GX-B1521/20-Y-24031	2024年1月28日	所检项目合格。	

139	GX-B1521/20-Y-24032	2024年1月28日	所检项目合格。	 A yellow CAT excavator is shown in a dark, possibly volcanic, environment. The excavator is positioned on a dark surface, and its arm is raised. A person in a white protective suit stands next to the machine for scale. The background shows a clear blue sky and distant mountains. A yellow date stamp '2024/1/14' is visible in the bottom right corner of the image.
140	GX-B1521/20-Y-24033	2024年1月28日	所检项目合格。	 A yellow CAT excavator is shown in a dark, possibly volcanic, environment. The excavator is positioned on a dark surface, and its arm is raised. Two people in protective suits stand next to the machine for scale. The background shows a clear blue sky and distant mountains. A yellow date stamp '2024/1/15' is visible in the bottom right corner of the image.

141	GX-B1521/20-Y-24034	2024年1月28日	所检项目合格。	
142	GX-B1521/20-Y-24035	2024年1月28日	所检项目合格。	

143	GX-B1521/20-Y-24036	2024年1月28日	所检项目合格。	
144	GX-B1521/20-Y-24037	2024年1月28日	所检项目合格。	

145	GX-B1521/20-Y-24038	2024年1月28日	所检项目合格。	
146	GX-B1539/22-Y-24001	2024年1月28日	所检项目合格。	

147	GX-B1539/22-Y-24002	2024年1月28日	所检项目合格。	
148	GX-B1522/20-Y-24003	2024年1月28日	所检项目合格。	

149	GX-B1522/20-Y-24004	2024年1月28日	所检项目合格。	
150	GX-B1522/20-Y-24005	2024年1月28日	所检项目合格。	

151	GX-B1522/20-Y-24006	2024年1月28日	所检项目合格。	
152	GX-B1522/20-Y-24007	2024年1月28日	所检项目合格。	

153	GX-B1522/20-Y-24008	2024年1月28日	所检项目合格。	
154	GX-B1522/20-Y-24009	2024年1月28日	所检项目合格。	

155	GX-B1522/20-Y-24010	2024年1月28日	所检项目合格。	
156	GX-B1522/20-Y-24011	2024年1月28日	所检项目合格。	

157	GX-B1522/20-Y-24012	2024年1月28日	所检项目合格。	
158	GX-B1522/20-Y-24013	2024年1月28日	所检项目合格。	

159	GX-B1521/20-Y-24001	2024年1月28日	所检项目合格。	
160	GX-B1521/20-Y-24002	2024年1月28日	所检项目合格。	

161	GX-B1539/22-Y-24003	2024年1月28日	所检项目合格。	 A yellow CAT wheel loader is shown at a construction site. The machine is parked on a dirt surface. A person is standing near the front of the loader. The date "2024/1/12" is visible in the bottom right corner of the image.
162	GX-B1521/20-Y-24003	2024年1月28日	所检项目合格。	 A yellow CAT tracked excavator is shown at a construction site. The machine is parked on a dirt surface. A person is standing near the front of the excavator. The date "2024/1/12" is visible in the bottom right corner of the image.

163	GX-B1521/20-Y-24004	2024年1月28日	所检项目合格。	
164	GX-B1521/20-Y-24005	2024年1月28日	所检项目合格。	

165	GX-B1521/20-Y-24006	2024年1月28日	所检项目合格。	
166	GX-B1521/20-Y-24007	2024年1月28日	所检项目合格。	

167	GX-B1521/20-Y-24008	2024年1月28日	所检项目合格。	
168	GX-B1521/20-Y-24009	2024年1月28日	所检项目合格。	



169	GX-B1521/20-Y-24010	2024年1月28日	所检项目合格。	
170	GX-B1521/20-Y-24011	2024年1月28日	所检项目合格。	



171	GX-B1521/20-Y-24012	2024年1月28日	所检项目合格。	
172	GX-B1521/20-Y-24013	2024年1月28日	所检项目合格。	

173	GX-B1521/20-Y-24014	2024年1月28日	所检项目合格。	
174	GX-B1521/20-Y-24015	2024年1月28日	所检项目合格。	

175	GX-B1521/20-Y-24016	2024年1月28日	所检项目合格。	 <p>A yellow CAT excavator with the number 16 on its boom is shown in a dark, industrial setting. Two workers in white protective suits are standing near the machine. A yellow timestamp '2024/1/13' is visible in the bottom right corner of the image.</p>
176	GX-B1521/20-Y-24017	2024年1月28日	所检项目合格。	 <p>A yellow CAT excavator with the number 17 on its boom is shown in a dark, industrial setting. Two workers in white protective suits are standing near the machine. A yellow timestamp '2024/1/13' is visible in the bottom right corner of the image.</p>

177	GX-B1521/20-Y-24018	2024年1月28日	所检项目合格。	
178	GX-B1521/20-Y-24019	2024年1月28日	所检项目合格。	

179	GX-B1321/20-Y-23664~23667	2024年1月29日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
180	GX-B1321/20-Y-23668~23670	2024年1月29日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	

181	GX-B1404/20-Y-23023	2024年1月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
182	GX-B1404/20-Y-23024	2024年1月29日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

183	GX-B1521/20-Y-24050	2024年1月28日	所检项目合格。	
184	GX-B1521/20-Y-24051	2024年1月28日	所检项目合格。	

185	GX-B1521/20-Y-24052	2024年1月28日	所检项目合格。	
186	GX-B1521/20-Y-24053	2024年1月28日	所检项目合格。	



187	GX-B1495/20-Y-231820~231829	2024年1月24日	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
188	GX-B1495/20-Y-231830~231832	2024年1月24日	本次共检高压防爆开关3台，3台高压防爆开关所检项目合格。	

189	GX-B1495/20-Y-231830~231832	2024年1月24日	所检项目合格。	 <p>A photograph showing a worker in a red uniform and helmet operating a piece of machinery. The worker is looking at a control panel with various buttons and lights. The date 2023/12/27 is visible in the bottom right corner of the image.</p>
190	GX-B1521/20-Y-23659	2024年1月24日	所检项目合格。	 <p>A photograph showing a worker in a red helmet and safety vest operating a piece of machinery. The worker is holding a tool or device and looking at the control panel. The date 2023/12/27 is visible in the bottom right corner of the image.</p>



191	GX-B1521/20-Y-23660	2024年1月24日	所检项目合格。	 <p>2023/12/31</p>
192	GX-B1521/20-Y-23661	2024年1月24日	所检项目合格。	 <p>2023/12/31</p>

193	GX-B1521/20-Y-23662	2024年1月24日	所检项目合格。	
194	GX-B1521/20-Y-23663	2024年1月24日	所检项目合格。	



195	GX-B1521/20-Y-23664	2024年1月24日	所检项目合格。	
196	GX-B1521/20-Y-23665	2024年1月24日	所检项目合格。	

197	GX-B1521/20-Y-23666	2024年1月24日	所检项目合格。	 A worker wearing a red hard hat and a camouflage jacket is seated inside the cab of a tracked vehicle. The worker is looking down at a handheld device. The interior of the cab is visible, showing various controls and a steering lever. A yellow date stamp "2023/12/31" is visible in the top right corner of the image.
198	GX-B1521/20-Y-23667	2024年1月24日	所检项目合格。	 A yellow tracked vehicle, labeled "SOLD", is parked on a dirt surface. Two workers in blue and brown uniforms and red hard hats are standing next to the vehicle. The background shows a clear blue sky and some distant structures. A yellow date stamp "2023/12/31" is visible in the bottom right corner of the image.

199	GX-B1521/20-Y-23668	2024年1月24日	所检项目合格。	
200	GX-B1495/20-Y-231801~231807	2024年1月28日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	

201	GX-B1495/20-Y-231808~231813	2024年1月28日	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。	
202	GX-B1495/20-Y-231814~231819	2024年1月28日	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。	

203	GX-B1310/21-Y-24007	2024年1月31日	符合标准要求。	 <p>2024/1/5</p>
204	GX-B1310/21-Y-24008	2024年1月31日	符合标准要求。	 <p>2024/1/5</p>

205	GX-B1310/21-Y-24009	2024年1月31日	符合标准要求。		
206	GX-B1310/21-Y-24010	2024年1月31日	符合标准要求。		

207	GX-B1310/21-Y-24011	2024年1月31日	符合标准要求。	
208	GX-B1310/21-Y-24012	2024年1月31日	符合标准要求。	

209	GX-B1310/21-Y-24013	2024年1月31日	符合标准要求。		
210	GX-B1310/21-Y-24014	2024年1月31日	符合标准要求。		

211	GX-B1310/21-Y-24015	2024年1月31日	符合标准要求。		
212	GX-B1310/21-Y-24016	2024年1月31日	符合标准要求。		

213	GX-B1310/21-Y-24017	2024年1月31日	符合标准要求。	
214	GX-B1310/21-Y-24018	2024年1月31日	符合标准要求。	

215	GX-B1310/21-Y-24019	2024年1月31日	符合标准要求。	 <p data-bbox="1518 485 1570 496">2024/1/8</p>
-----	---------------------	------------	---------	---