

序号	报告编号	发布日期	结论	影像资料
179	GX-B1495/20-2-24224~24227	2024/5/26	所检项目合格	
180	GX-B1495/20-24140~24144	2024/5/26	所检项目合格	

181	GX-B1559/22-2-24005	2024/5/26	所检项目合格	
182	GX-B1321/20-2-24095	2024. 5. 24	所检项目合格。	
183	GX-B1321/20-2-24129~24136	2024. 5. 24	本次共检电力电缆8条， 8条电力电缆所检项目合格。	

184	GX-B1321/20-2-24137~24146	2024. 5. 24	本次共检电力电缆 10条，10条电力电缆所 检项目合格。	 2024/04/10
185	GX-B1309/21-2-24011	2024/5/26	所检项目合格	 2024/05/20
186	GX-B1500/21-2-24054	2024/5/26	综合判定：合格	 2024/05/20

187	GX-B1500/21-2-24055	2024/5/26	综合判定：合格		
188	GX-B1500/21-2-24056	2024/5/26	综合判定：合格		
189	GX-B1500/21-2-24057	2024/5/26	综合判定：合格		

190	GX-B1495/20-2-24145~24160	2024/5/26	所检项目合格	
191	GX-B1495/20-2-24161~24168	2024/5/26	所检项目合格	
192	GX-B1451/20-2-24275~24281	2024/5/26	所检项目合格	

193	GX-B1451/20-2-24282~24288	2024/5/26	所检项目合格	
194	GX-B1499/23-2-24061	2024/5/26	所检项目合格	
195	GX-B1499/23-2-24062	2024/5/26	所检项目合格	

196	GX-B1499/23-2-24063	2024/5/26	所检项目合格	 <p>2024-04-18</p>
197	GX-B1499/23-2-24052	2024. 5. 26	<p>吨水百米电耗超限。 除吨水百米电耗超限外，其余所检项目合格。</p>	 <p>2024/5/2</p>
198	GX-B1499/23-2-24053	2024. 5. 26	<p>吨水百米电耗大于 0.5kW·h。 除吨水百米电耗不合格外，其余所检项目合格。</p>	 <p>2024/5/2</p>

199	GX-B1499/23-2-24054	2024. 5. 26	<p>吨水百米电耗大于 0.5kW·h。 除吨水百米电耗不 合格外，其余所检 项目合格。</p>	
200	GX-B1539/22-2-24004	2024. 5. 26	<p>所检项目合格。</p>	
201	GX-B1539/22-2-24005	2024. 5. 26	<p>所检项目合格。</p>	

202	GX-B1539/22-2-24006	2024. 5. 26	所检项目合格。	 A yellow wheel loader is shown in a tunnel setting. A worker in a blue uniform and red helmet is visible in the operator's seat. The loader is positioned on a dirt or gravel surface. A timestamp '2024.05.12' is visible in the bottom right corner of the image.
203	GX-B1539/22-2-24007	2024. 5. 26	所检项目合格。	 A worker in a blue uniform and red helmet is standing in a tunnel. The worker is holding a flashlight and looking towards the camera. The tunnel walls are rocky and there are some equipment and cables visible in the background. A timestamp '2024.05.12' is visible in the bottom right corner of the image.
204	GX-B1539/22-2-24008	2024. 5. 26	所检项目合格。	 A worker in a blue uniform and red helmet is standing in a tunnel. The worker is holding a flashlight and looking towards the camera. The tunnel walls are rocky and there are some equipment and cables visible in the background. A timestamp '2024.05.12' is visible in the bottom right corner of the image.

205	GX-B1539/22-2-24009	2024. 5. 26	所检项目合格。		
206	GX-B1539/22-2-24010	2024. 5. 26	所检项目合格。		
207	GX-B1539/22-2-24011	2024. 5. 26	所检项目合格。		

208	GX-B1539/22-2-24012	2024. 5. 26	所检项目合格。	
209	GX-B1539/22-2-24013	2024. 5. 26	所检项目合格。	
210	GX-B1598/21-2-24102	2024. 5. 27	<p>实测钢丝绳有效截面积 损失百分比最大为 1.37%，小于5%为正常。</p>	


211	GX-B1598/21-2-24103	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.34%，小于5%为正常。	
212	GX-B1598/21-2-24104	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.19%，小于5%为正常。	
213	GX-B1598/21-2-24105	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.24%，小于5%为正常。	

214	GX-B1598/21-2-24106	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.06%，小于5%为正常。	
215	GX-B1598/21-2-24107	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 0.85%，小于5%为正常。	
216	GX-B1598/21-2-24108	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.15%，小于5%为正常。	

217	GX-B1598/21-2-24109	2024. 5. 27	实测钢丝绳有效截面积 损失百分比最大为 1.19%，小于5%为正常。	
218	GX-B1415/22-2-24007	2024. 5. 27	综合判定：合格。 。	
219	GX-B1535/21-2-24001	2024. 5. 27	所检项目合格。	

220	GX-B1310/21-2-24116	2024. 5. 27	符合标准要求。	
221	GX-B1310/21-2-24117	2024. 5. 27	符合标准要求。	
222	GX-B1310/21-2-24118	2024. 5. 27	符合标准要求。	

223	GX-B1310/21-2-24119	2024. 5. 27	符合标准要求。	
224	GX-B1428/21-2-24119	2024. 5. 27	无缺陷迹痕显示。	
225	GX-B1310/21-2-24120	2024. 5. 27	符合标准要求。	

226	GX-B1428/21-2-24120	2024. 5. 27	无缺陷迹痕显示。	
227	GX-B1310/21-2-24121	2024. 5. 27	符合标准要求。	
228	GX-B1428/21-2-24121	2024. 5. 27	无缺陷迹痕显示。	

229	GX-B1310/21-2-24122	2024. 5. 27	符合标准要求。	
230	GX-B1428/21-2-24122	2024. 5. 27	无缺陷迹痕显示。	
231	GX-B1310/21-2-24123	2024. 5. 27	符合标准要求。	

232	GX-B1310/21-2-24124	2024. 5. 27	符合标准要求。	
233	GX-B1310/21-2-24125	2024. 5. 27	符合标准要求。	
234	GX-B1310/21-2-24126	2024. 5. 27	符合标准要求。	

235	GX-B1310/21-2-24127	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>
236	GX-B1310/21-2-24128	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>
237	GX-B1310/21-2-24129	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>

238	GX-B1310/21-2-24130	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>
239	GX-B1310/21-2-24131	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>
240	GX-B1310/21-2-24132	2024. 5. 27	符合标准要求。	 <p>2024/4/6</p>

241	GX-B1310/21-2-24133	2024. 5. 27	符合标准要求。	 <p>2024/4/8</p>
242	GX-B1310/21-2-24134	2024. 5. 27	符合标准要求。	 <p>2024/4/3</p>
243	GX-B1310/21-2-24135	2024. 5. 27	符合标准要求。	 <p>2024/4/3</p>

244	GX-B1310/21-2-24136	2024. 5. 27	符合标准要求。	 <p>2024/4/17</p>
245	GX-B1310/21-2-24137	2024. 5. 27	符合标准要求。	 <p>2024/4/17</p>
246	GX-B1428/21-2-24137	2024. 5. 27	无缺陷痕迹显示。	 <p>2024/4/17</p>

247	GX-B1310/21-2-24138	2024. 5. 27	符合标准要求。	 <p>2024/4/18</p>
248	GX-B1428/21-2-24138	2024. 5. 27	无缺陷迹痕显示。	 <p>2024/4/18</p>
249	GX-B1310/21-2-24139	2024. 5. 27	符合标准要求。	 <p>2024/4/18</p>

250	GX-B1310/21-2-24140	2024. 5. 27	符合标准要求。	
251	GX-B1310/21-2-24142	2024. 5. 27	符合标准要求。	
252	GX-B1310/21-2-24143	2024. 5. 27	符合标准要求。	

253	GX-B1310/21-2-24144	2024. 5. 27	符合标准要求。	
254	GX-B1598/21-2-24114	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 0.95%，小于5%为正常。	
255	GX-B1598/21-2-24116	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 0.69%，小于5%为正常。	

256	GX-B1598/21-2-24117	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 1.05%，小于5%为正常。	
257	GX-B1598/21-2-24118	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 0.90%，小于5%为正常。	
258	GX-B1598/21-2-24119	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 0.79%，小于5%为正常。	

259	GX-B1547/20-24011~24013	2024/5/29	所检项目合格	
260	GX-B1547/20-24014~24016	2024/5/29	所检项目合格	
261	GX-B1495/20-2-24265~24279	2024/5/29	所检项目合格	

262	GX-B1495/20-2-24280~24293	2024/5/29	所检项目合格	
263	GX-B1495/20-2-24294~24304	2024/5/29	所检项目合格	
264	GX-B1495/20-2-24305~24313	2024/5/29	所检项目合格	

265	GX-B1495/20-2-24314~24316	2024/5/29	所检项目合格	
266	GX-B1495/20-2-24317~24318	2024/5/29	所检项目合格	
267	GX-B1322/21-2-24142~24146	2024. 5. 29	本次共检验电力电缆5条，5条所检项目合格。	

268	GX-B1322/21-2-24147~24151	2024. 5. 30	本次共检验电力电缆5条，5条所检项目合格。	 <p>2024/04/21</p>
269	GX-B1321/20-2-24239~24246	2024. 5. 30	本次共检电力电缆8条，8条电力电缆所检项目合格。	 <p>2024/04/30</p>
270	GX-B1321/20-2-24231~24238	2024. 5. 30	本次共检电力电缆8条，8条电力电缆所检项目合格。	 <p>2024/04/27</p>

271	GX-B1306/23-2-24015	2024. 5. 30	综合判定：合格。	
272	GX-B1306/23-2-24016	2024. 5. 30	综合判定：合格。	
273	GX-B1306/23-2-24017	2024. 5. 30	综合判定：合格。	

274	GX-B1321/20-2-24197~24198	2024. 5. 30	本次共检电力电缆2条， 2条电力电缆所检项目合格。	 2024/04/19
275	GX-B1321/20-0-24114~24123	2024. 5. 30	本次共检电力电缆 10条，10条电力电缆所 检项目合格。	 2024/04/13
276	GX-B1321/20-0-24147~24157	2024. 5. 30	本次共检电力电缆 11条，11条电力电缆所 检项目合格。	 2024/04/12

277	GX-B1321/20-0-24158~24165	2024. 5. 30	本次共检电力电缆8条， 8条电力电缆所检项目合格。	
278	GX-B1598/21-2-24115	2024/5/29	实测钢丝绳有效截面积 损失百分比最大为 0.82%，小于5%为正常。	
279	GX-B1495/20-2-24320~24332	2024/5/31	所检项目合格	