

序号	报告编号	发布日期	结论	影像资料
1	GX-B1522/20-Y-24043	2024年6月3日	所检项目合格。	
2	GX-B1522/20-Y-24044	2024年6月3日	所检项目合格。	



3	GX-B1522/20-Y-24045	2024年6月3日	所检项目合格。	
4	GX-B1522/20-Y-24046	2024年6月3日	所检项目合格。	

5	GX-B1522/20-Y-24047	2024年6月3日	所检项目合格。	
6	GX-B1522/20-Y-24048	2024年6月3日	所检项目合格。	

7	GX-B1522/20-Y-24049	2024年6月3日	所检项目合格。	
8	GX-B1522/20-Y-24050	2024年6月3日	所检项目合格。	

9	GX-B1522/20-Y-24051	2024年6月3日	所检项目合格。	
10	GX-B1522/20-Y-24052	2024年6月3日	所检项目合格。	

11	GX-B1539/22-Y-24189	2024. 6. 3	所检项目合格。	
12	GX-B1539/22-Y-24190	2024. 6. 3	所检项目合格。	

13	GX-B1539/22-Y-24191	2024. 6. 3	所检项目合格。	
14	GX-B1539/22-Y-24192	2024. 6. 3	所检项目合格。	

15	GX-B1539/22-Y-24193	2024. 6. 3	所检项目合格。	
16	GX-B1539/22-Y-24194	2024. 6. 3	所检项目合格。	

17	GX-B1539/22-Y-24195	2024. 6. 3	所检项目合格。	
18	GX-B1539/22-Y-24196	2024. 6. 3	所检项目合格。	

19	GX-B1539/22-Y-24197	2024. 6. 3	所检项目合格。	
20	GX-B1539/22-Y-24198	2024. 6. 3	所检项目合格。	

21	GX-B1539/22-Y-24199	2024. 6. 3	所检项目合格。	
22	GX-B1539/22-Y-24200	2024. 6. 3	所检项目合格。	

23	GX-B1521/20-Y-24353	2024. 6. 3	所检项目合格。	
24	GX-B1521/20-Y-24354	2024. 6. 3	所检项目合格。	

25	GX-B1521/20-Y-24355	2024. 6. 3	所检项目合格。	
26	GX-B1521/20-Y-24356	2024. 6. 3	所检项目合格。	

27	GX-B1521/20-Y-24357	2024. 6. 3	所检项目合格。	
28	GX-B1521/20-Y-24358	2024. 6. 3	所检项目合格。	

29	GX-B1521/20-Y-24359	2024. 6. 3	所检项目合格。	
30	GX-B1521/20-Y-24360	2024. 6. 3	所检项目合格。	

31	GX-B1521/20-Y-24361	2024. 6. 3	所检项目合格。	
32	GX-B1521/20-Y-24362	2024. 6. 3	所检项目合格。	

33	GX-B1521/20-Y-24363	2024. 6. 3	所检项目合格。	
34	GX-B1521/20-Y-24364	2024. 6. 3	所检项目合格。	

35	GX-B1521/20-Y-24365	2024. 6. 3	所检项目合格。	
36	GX-B1521/20-Y-24366	2024. 6. 3	所检项目合格。	

37	GX-B1521/20-Y-24367	2024. 6. 3	所检项目合格。	
38	GX-B1521/20-Y-24368	2024. 6. 3	所检项目合格。	

39	GX-B1521/20-Y-24369	2024. 6. 3	所检项目合格。	
40	GX-B1521/20-Y-24370	2024. 6. 3	所检项目合格。	

41	GX-B1521/20-Y-24371	2024. 6. 3	所检项目合格。	
42	GX-B1521/20-Y-24372	2024. 6. 3	所检项目合格。	

43	GX-B1521/20-Y-24342	2024. 6. 4	所检项目合格。	
44	GX-B1521/20-Y-24343	2024. 6. 4	所检项目合格。	

45	GX-B1521/20-Y-24344	2024. 6. 4	所检项目合格。	
46	GX-B1521/20-Y-24345	2024. 6. 4	所检项目合格。	

47	GX-B1521/20-Y-24346	2024. 6. 4	所检项目合格。	
48	GX-B1521/20-Y-24347	2024. 6. 4	所检项目合格。	

49	GX-B1521/20-Y-24348	2024. 6. 4	所检项目合格。	 <p>A photograph of a yellow excavator in a dark, industrial setting, possibly a quarry or mine. The excavator is positioned in the center, with its arm and bucket visible. The background is dark and hazy. A yellow timestamp '2024/5/19' is visible in the bottom right corner of the image.</p>
50	GX-B1521/20-Y-24349	2024. 6. 4	所检项目合格。	 <p>A photograph of a yellow tracked excavator in a bright, outdoor setting. The excavator is positioned in the center, with its arm and bucket visible. A person in a white shirt and red cap is standing next to the excavator for scale. The background shows a clear blue sky and a hazy horizon. A yellow timestamp '2024/5/19' is visible in the bottom right corner of the image.</p>

51	GX-B1521/20-Y-24350	2024. 6. 4	所检项目合格。	
52	GX-B1521/20-Y-24351	2024. 6. 4	所检项目合格。	

53	GX-B1521/20-Y-24352	2024. 6. 4	所检项目合格。	
54	GX-B1521/20-Y-24389	2024年6月4日	所检项目合格。	

55	GX-B1521/20-Y-24390	2024年6月4日	所检项目合格。	
56	GX-B1521/20-Y-24391	2024年6月4日	所检项目合格。	

57	GX-B1521/20-Y-24392	2024年6月4日	所检项目合格。	
58	GX-B1521/20-Y-24393	2024年6月4日	所检项目合格。	

59	GX-B1521/20-Y-24394	2024年6月4日	所检项目合格。	
60	GX-B1521/20-Y-24395	2024年6月4日	所检项目合格。	

61	GX-B1521/20-Y-24396	2024年6月4日	所检项目合格。	
62	GX-B1521/20-Y-24397	2024年6月4日	所检项目合格。	

63	GX-B1521/20-Y-24398	2024年6月4日	所检项目合格。	
64	GX-B1521/20-Y-24399	2024年6月4日	所检项目合格。	

65	GX-B1521/20-Y-24400	2024年6月4日	所检项目合格。	
66	GX-B1521/20-Y-24401	2024年6月4日	所检项目合格。	

67	GX-B1521/20-Y-24402	2024年6月4日	所检项目合格。	
68	GX-B1521/20-Y-24403	2024年6月4日	所检项目合格。	

69	GX-B1521/20-Y-24404	2024年6月4日	所检项目合格。	 A yellow SANY excavator is shown at a construction site. Two workers in safety gear are standing near the machine. The background shows a clear blue sky and a dirt area. A yellow timestamp '2024/6/29' is visible in the bottom right corner of the photo.
70	GX-B1521/20-Y-24405	2024年6月4日	所检项目合格。	 A yellow SANY excavator is shown at a construction site. Two workers in safety gear are standing near the machine. The background shows a clear blue sky and a dirt area. A yellow timestamp '2024/6/25' is visible in the bottom right corner of the photo.

71	GX-B1521/20-Y-24406	2024年6月4日	所检项目合格。	 A yellow excavator is shown at a construction site. Two workers in red and white safety gear are standing near the machine. The background shows a clear blue sky and some distant hills.
72	GX-B1521/20-Y-24407	2024年6月4日	所检项目合格。	 A yellow excavator with the number '15' on its arm is shown at a construction site. Two workers in red and white safety gear are standing near the machine. The background shows a clear blue sky and some distant hills. A date stamp '2024/6/26' is visible in the bottom right corner of the image.

73	GX-B1521/20-Y-24408	2024年6月4日	所检项目合格。	 A yellow tracked excavator with the number '16' on its boom is parked on a dirt surface. Two workers in red safety gear are standing near the machine. A yellow date stamp '2024/6/25' is visible in the bottom right corner of the photo.
74	GX-B1521/20-Y-24409	2024年6月4日	所检项目合格。	 A yellow tracked excavator with the number '17' on its boom is parked on a dirt surface. Two workers in red safety gear are standing near the machine. A yellow date stamp '2024/6/25' is visible in the bottom right corner of the photo.

75	GX-B1521/20-Y-24410	2024年6月4日	所检项目合格。	
76	GX-B1521/20-Y-24411	2024年6月4日	所检项目合格。	

77	GX-B1539/22-Y-24209	2024年6月4日	所检项目合格。	
78	GX-B1539/22-Y-24210	2024年6月4日	所检项目合格。	

79	GX-B1539/22-Y-24211	2024年6月4日	所检项目合格。	 A yellow L953H wheel loader is parked on a dirt surface. A worker in a white uniform and a red hard hat stands next to the front of the machine. The background shows a clear blue sky and some distant hills. A yellow timestamp '2024/6/22' is visible in the bottom right corner of the photo.
80	GX-B1539/22-Y-24212	2024年6月4日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers, one in a white uniform and red hard hat, and another in a green uniform and yellow hard hat, stand next to the machine. The background shows a clear blue sky and some distant hills. A yellow timestamp '2024/6/22' is visible in the bottom right corner of the photo.

81	GX-B1539/22-Y-24213	2024年6月4日	所检项目合格。	
82	GX-B1539/22-Y-24214	2024年6月4日	所检项目合格。	

83	GX-B1539/22-Y-24215	2024年6月4日	所检项目合格。	
84	GX-B1539/22-Y-24216	2024年6月4日	所检项目合格。	

85	GX-B1539/22-Y-24217	2024年6月4日	所检项目合格。	
86	GX-B1539/22-Y-24218	2024年6月4日	所检项目合格。	

87	GX-B1539/22-Y-24219	2024年6月4日	所检项目合格。	
88	GX-B1539/22-Y-24220	2024年6月4日	所检项目合格。	

89	GX-B1547/20-Y-24087~24093	2024年6月4日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	
90	GX-B1547/20-Y-24094~24103	2024年6月4日	本次共检继电保护装置10台，10台继电保护装置所检项目合格。	

91	GX-B1547/20-Y-24104~24109	2024年6月4日	本次共检继电保护装置6台，6台继电保护装置所检项目合格。	
92	GX-B1547/20-Y-24110~24118	2024年6月4日	本次共检继电保护装置9台，9台继电保护装置所检项目合格。	

93	GX-B1547/20-Y-24119~24133	2024年6月4日	本次共检继电保护装置15台，15台继电保护装置所检项目合格。	 A photograph showing a worker in a white uniform and black cap inspecting a control panel in a room filled with electrical cabinets. The worker is standing and looking at the panel. A yellow timestamp '2024/4/8' is visible in the bottom right corner of the image.
94	GX-B1547/20-Y-24134~24136	2024年6月4日	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	 A photograph showing two workers in a room with electrical cabinets. One worker in a red uniform and yellow cap is standing and inspecting a panel. Another worker in a grey uniform and red cap is kneeling and working on a lower panel. A yellow timestamp '2024/4/8' is visible in the bottom right corner of the image.

95	GX-B1547/20-Y-24137	2024年6月4日	所检项目合格。	
96	GX-B1547/20-Y-24138~24150	2024年6月4日	本次共检继电保护装置13台，13台继电保护装置所检项目合格。	

97	GX-B1547/20-Y-24151~24157	2024年6月4日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	
98	GX-B1547/20-Y-24158~24167	2024年6月4日	本次共检继电保护装置10台，10台继电保护装置所检项目合格。	


99	GX-B1547/20-Y-24168~24174	2024年6月4日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	
100	GX-B1547/20-Y-24175~24181	2024年6月4日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	

101	GX-B1547/20-Y-24182~24192	2024年6月4日	本次共检继电保护装置11台，11台继电保护装置所检项目合格。	
102	GX-B1547/20-Y-24193~24194	2024年6月4日	本次共检继电保护装置2台，2台继电保护装置所检项目合格。	

103	GX-B1547/20-Y-24195~24201	2024年6月4日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	
104	GX-B1547/20-Y-24202	2024年6月4日	所检项目合格。	

105	GX-B1547/20-Y-24203	2024年6月4日	所检项目合格。	
106	GX-B1547/20-Y-24204~24214	2024年6月4日	本次共检继电保护装置11台，11台继电保护装置所检项目合格。	

107	GX-B1547/20-Y-24215~24226	2024年6月4日	本次共检继电保护装置12台，12台继电保护装置所检项目合格。	
108	GX-B1547/20-Y-24227~24237	2024年6月4日	本次共检继电保护装置11台，11台继电保护装置所检项目合格。	

109	GX-B1547/20-Y-24238~24245	2024年6月4日	本次共检继电保护装置8台，8台继电保护装置所检项目合格。	 A photograph showing two workers in white protective suits and red hard hats inspecting electrical equipment in a control room. One worker is standing and reaching up to inspect a panel, while the other is kneeling and working on a lower panel. The equipment is housed in a rack with various meters and switches. A yellow timestamp '2024/4/17' is visible in the bottom right corner of the photo.
-----	---------------------------	-----------	------------------------------	---