





序号	报告编号	发布日期	结论	影像资料
1	GX-B1377/22-F-24242	2024. 8. 6	除击穿电压不合格外，其余所检项目合格。	 A photograph showing two female technicians in light blue short-sleeved shirts and dark skirts working at a laboratory bench. They are looking at equipment. A timestamp '2024.7.31' is visible in the bottom right corner of the image.
2	GX-B1378/22-F-24182	2024. 8. 6	所检项目合格。	 A photograph showing two female technicians in light blue short-sleeved shirts and dark skirts operating a large piece of laboratory equipment. One technician is adjusting a dial on the machine. A timestamp '2024.7.31' is visible in the bottom right corner of the image.
3	GX-B1502/21-F-24050	2024. 8. 6	III类，不易自燃。	

4	GX-B1501/21-F-24050	2024. 8. 6	煤尘不具有爆炸性	
5	GX-B1600/21-F-24009	2024. 8. 6	可不注水煤层	
6	GX-B1378/22-F-24183~F-24188	2024. 8. 12	缩机油油样6个，6个油样所检项目	
7	GX-B1489/21-F-24062	2024. 8. 16	所检项目合格	

8	GX-B1377/22-F-24243	2024. 8. 16	所检项目合格	
9	GX-B1377/22-F-24244	2024. 8. 16	所检项目合格	
10	GX-B1377/22-F-24245	2024. 8. 16	所检项目合格	

11	GX-B1492/21-F-24062	2024. 8. 16	所检项目合格	
12	GX-B1489/21-F-24061	2024. 8. 16	所检项目合格	
13	GX-B1378/22-F-24189~F-24193	2024. 8. 14	所检项目合格	

14	GX-B1378/22-F-24194	2024. 8. 14	所检项目合格	
----	---------------------	-------------	--------	---