

序号	报告编号	发布日期	结论	影像资料
48	GX-B1310/21-5-24295	2024/9/18	符合标准要求。	 A black and white photograph showing a worker wearing a hard hat and safety glasses, working on a mechanical component. The worker is wearing a dark safety vest with reflective stripes. The background shows industrial equipment. A date stamp '2024/9/9' is visible in the bottom right corner of the image.
49	GX-B1310/21-5-24296	2024/9/18	符合标准要求。	 A black and white photograph showing a worker wearing a white protective suit and a hard hat, working on a mechanical component. The worker is wearing a white safety vest with reflective stripes. The background shows industrial equipment. A date stamp '2024/9/9' is visible in the bottom right corner of the image.

50	GX-B1310/21-5-24297	2024. 9. 18	符合标准要求。	
51	GX-B1310/21-5-24298	2024. 9. 18	符合标准要求。	

52	GX-B1310/21-5-24299	2024. 9. 18	符合标准要求。	 A photograph showing a worker in a light-colored uniform and cap standing on a wooden ladder. The worker is positioned next to a large, dark grey cylindrical metal tank. The worker appears to be inspecting or working on the top edge of the tank. The background is a clear blue sky. A yellow timestamp '2024/9/5' is visible in the bottom right corner of the image.
53	GX-B1310/21-5-24300	2024. 9. 18	符合标准要求。	 A photograph showing a worker in a light-colored uniform and cap standing on a wooden ladder. The worker is positioned next to a large, dark grey cylindrical metal tank. The worker appears to be inspecting or working on the top edge of the tank. The background is a clear blue sky. A yellow timestamp '2024/9/5' is visible in the bottom right corner of the image.

54	GX-B1310/21-5-24301	2024. 9. 18	符合标准要求。	
55	GX-B1310/21-5-24302	2024. 9. 18	符合标准要求。	

56	GX-B1310/21-5-24303	2024. 9. 18	符合标准要求。	
57	GX-B1310/21-5-24304	2024. 9. 18	符合标准要求。	

58	GX-B1310/21-5-24305	2024. 9. 18	符合标准要求。	
59	GX-B1310/21-5-24306	2024. 9. 18	符合标准要求。	

60	GX-B1310/21-5-24307	2024. 9. 18	符合标准要求。			
61	GX-B1310/21-5-24308	2024. 9. 18	符合标准要求。			

62	GX-B1310/21-5-24309	2024. 9. 18	符合标准要求。			
63	GX-B1310/21-5-24310	2024. 9. 18	符合标准要求。			

64	GX-B1310/21-5-24311	2024. 9. 18	符合标准要求。	 A worker in a white uniform and helmet is standing on a platform, working on a large black industrial vessel. The vessel is part of a larger structure with orange scaffolding. The date 2024/9/18 is visible in the bottom right corner of the image.
65	GX-B1310/21-5-24312	2024. 9. 18	符合标准要求。	 A worker in a white uniform and helmet is working on a red industrial vessel. The worker is focused on a specific part of the vessel, possibly a valve or flange. The date 2024/9/18 is visible in the bottom right corner of the image.

66	GX-B1310/21-5-24313	2024. 9. 18	符合标准要求。	
67	GX-B1310/21-5-24314	2024. 9. 18	符合标准要求。	

68	GX-B1310/21-5-24315	2024. 9. 18	符合标准要求。	
69	GX-B1310/21-5-24248	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	

70	GX-B1310/21-5-24249	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。		
71	GX-B1310/21-5-24250	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。		

72	GX-B1310/21-5-24251	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	 <p>A worker wearing a red helmet and safety harness is kneeling on a blue metal surface, performing ultrasonic testing. A yellow date stamp '2024/9/24' is visible in the bottom right corner of the photo.</p>
73	GX-B1310/21-5-24252	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	 <p>A worker wearing a red helmet and safety harness is kneeling on a blue metal surface, performing ultrasonic testing. The background shows a landscape with mountains and a cloudy sky. A yellow date stamp '2024/8/24' is visible in the bottom right corner of the photo.</p>

74	GX-B1310/21-5-24253	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	 A worker wearing a red helmet, safety glasses, and a grey safety harness is performing ultrasonic testing on a blue-painted steel structure. The worker is holding a device and looking at the results. The background shows a hazy landscape with hills. A yellow timestamp '2024/8/24' is visible in the bottom right corner of the photo.
75	GX-B1310/21-5-24254	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	 A worker wearing a red helmet, safety glasses, and a grey safety harness is performing ultrasonic testing on a blue-painted steel structure. The worker is holding a device and looking at the results. The background shows a hazy landscape with hills. A yellow timestamp '2024/8/24' is visible in the bottom right corner of the photo.

76	GX-B1310/21-5-24255	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	
77	GX-B1310/21-5-24256	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	

78	GX-B1310/21-5-24257	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	
79	GX-B1310/21-5-24258	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	

80	GX-B1310/21-5-24259	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	 A photograph showing two workers in safety gear (hard hats, safety harnesses) performing ultrasonic testing on a blue steel structure. One worker is kneeling and using a device, while the other stands nearby. A red safety rope is visible. The date '2024/8/24' is printed in the bottom right corner of the image.
81	GX-B1310/21-5-24260	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	 A photograph showing a worker in safety gear (red hard hat, safety harness) performing ultrasonic testing on a blue steel structure. The worker is kneeling and using a device. The date '2024/8/24' is printed in the bottom right corner of the image.

82	GX-B1310/21-5-24261	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	
83	GX-B1310/21-5-24262	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	

84	GX-B1310/21-5-24263	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	
85	GX-B1310/21-5-24264	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》3级要求。	

86	GX-B1310/21-5-24265	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	
87	GX-B1310/21-5-24266	2024. 9. 18	符合 GB/T 29712-2023 《焊缝无损检测 超声检测 验收等级》2级要求。	

88	GX-B1310/21-5-24267	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》3级要求。	
89	GX-B1310/21-5-24268	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》3级要求。	

90	GX-B1310/21-5-24269	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》3级要求。	
91	GX-B1310/21-5-24270	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》3级要求。	

92	GX-B1310/21-5-24271	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》2级要求。	
93	GX-B1310/21-5-24272	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》2级要求。	

94	GX-B1310/21-5-24273	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》2级要求。	
95	GX-B1310/21-5-24274	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》2级要求。	

96	GX-B1310/21-5-24275	2024. 9. 18	符合GB/T 29712-2023《焊缝无损检测 超声检测 验收等级》3级要求。	
97	GX-B1312/20-5-24010	2024. 9. 19	所检项目合格	

98	GX-B1328/20-5-24139	2024. 9. 20	本次共检携带式接地和接地短路装置25套，25套携带式接地和接地短路装置合格。	
99	GX-B1310/21-5-24316	2024. 9. 20	符合标准要求。	

100	GX-B1310/21-5-24317	2024. 9. 20	符合标准要求。	
101	GX-B1310/21-5-24318	2024. 9. 20	符合标准要求。	

102	GX-B1310/21-5-24319	2024. 9. 20	符合标准要求。	
103	GX-B1310/21-5-24320	2024. 9. 20	符合标准要求。	

104	GX-B1310/21-5-24321	2024. 9. 20	符合标准要求。	
105	GX-B1310/21-5-24322	2024. 9. 20	符合标准要求。	

106	GX-B1310/21-5-24323	2024. 9. 20	符合标准要求。	 A photograph showing a worker in a grey uniform and hard hat inspecting a large green and red industrial machine. The worker is looking into a circular opening on the machine. A yellow timestamp '2024/9/9' is visible in the bottom right corner of the image.
107	GX-B1310/21-5-24324	2024. 9. 20	符合标准要求。	 A photograph showing a worker in a grey uniform and hard hat operating a large green and red industrial machine. The worker is using a tool to adjust or inspect a component of the machine. A yellow timestamp '2024/9/9' is visible in the bottom right corner of the image.

108	GX-B1310/21-5-24325	2024. 9. 20	符合标准要求。	
109	GX-B1310/21-5-24326	2024. 9. 20	符合标准要求。	

110	GX-B1310/21-5-24327	2024. 9. 20	符合标准要求。	 A close-up photograph showing two workers in safety gear (hard hats and work clothes) inspecting a green industrial machine. One worker is pointing at a circular opening on the machine. A yellow timestamp '2024/9/9' is visible in the bottom right corner of the image.
111	GX-B1310/21-5-24328	2024. 9. 20	符合标准要求。	 A photograph showing a worker in safety gear (blue hard hat and work clothes) inspecting a green industrial machine. The worker is holding a device, possibly a camera or a measuring tool. A yellow timestamp '2024/9/9' is visible in the bottom right corner of the image.