

序号	报告编号	发布日期	结论	影像资料
34	GX-B1378/22-F-24218~F-24219	2024. 9. 24	本次共检空气压缩机油油样2个，2个油样所检项目合格	 A photograph showing two female technicians in light blue lab coats working in a laboratory. They are standing in front of a piece of equipment with a monitor. One technician is pointing at the screen while the other looks on. The date '2024.9.19' is visible in the bottom right corner of the photo.
35	GX-B1378/22-F-24220	2024. 9. 24	所检项目合格	 A photograph showing two female technicians in light blue lab coats working in a laboratory. They are standing in front of a piece of equipment with a monitor. One technician is pointing at the screen while the other looks on. The date '2024.9.19' is visible in the bottom right corner of the photo.

36	GX-B1378/22-F-24221~F-24223	2024. 9. 24	本次共检空气压缩机油油样3个，3个油样所检项目合	 <p>2024.9.19</p>
37	GX-B1378/22-F-24224	2024. 9. 24	所检项目合格	 <p>2024.9.19</p>

38	GX-B1377/22-F-24280	2024. 9. 25	所检项目合格	
39	GX-B1377/22-F-24281	2024. 9. 25	所检项目合格	

40	GX-B1378/22-F-24225~24226	2024. 9. 25	所检项目合格	
41	GX-B1378/22-F-24227~24228	2024. 9. 25	所检项目合格	

42	GX-B1489/21-F-24079	2024. 9. 26	所检项目合格	
43	GX-B1489/21-F-24080	2024. 9. 26	所检项目合格	

44	GX-B1489/21-F-24081	2024. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are standing at a desk with a piece of equipment that has a circular component. One person is adjusting the equipment while the other looks on. The date '2024.9.24' is visible in the bottom right corner of the image.
45	GX-B1489/21-F-24082	2024. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory setting. They are standing in front of a piece of equipment, possibly a biosafety cabinet or a specialized workstation. One person is holding a smartphone, and they appear to be discussing something. The date '2024.9.24' is visible in the bottom right corner of the image.

46	GX-B1489/21-F-24083	2024. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a white lab coat, is standing and looking at a piece of equipment. The other person, wearing a light blue shirt, is also looking at the equipment. The equipment appears to be a piece of scientific or industrial machinery. A timestamp '2024.9.24' is visible in the bottom right corner of the photo.
47	GX-B1460/22-F-24007	2024. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory. They are standing next to a large, white, rectangular piece of equipment. One person is looking at the equipment, while the other is looking down. The equipment has some text on it, including 'HAWAIIAN'. A timestamp '2024.9.24' is visible in the bottom right corner of the photo.

48	GX-B1492/21-F-24064~24065	2024. 9. 26	所检项目合格	
49	GX-B1492/21-F-24066	2024. 9. 26	所检项目合格	

50	GX-B1492/21-F-24067	2024. 9. 26	所检项目合格	
51	GX-B1489/21-F-24084~F-24087	2024. 9. 29	本次共检液压油油样4个， 4个油样所检项目合格。	

52	GX-B1378/22-F-24229	2024. 9. 29	所检项目合格。	 A photograph showing two individuals in white lab coats working in a laboratory. One person is holding a mobile device, possibly a tablet or smartphone, and the other is looking at it. They are standing in front of a piece of equipment, likely a biosafety cabinet or a similar laboratory instrument. The date '2024.9.26' is visible in the bottom right corner of the photo.
53	GX-B1600/21-F-24013	2024. 9. 29	3#煤层为可不注水煤层。	
54	GX-B1600/21-F-24012	2024. 9. 29	可不注水煤层	